

Cleanup Site Details

Cleanup Site ID: 9951

Cleanup Site ID: 9951 Facility/Site ID: 63168342 UST ID: 6178 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Glitsa American Inc [Glossary](#)

Alternate Names: GLITSA AMERICAN, Glitsa American Inc, GLITSA AMERICAN INCORPORATED, Tenor Co

LOCATION

Address: 327 S KENYON ST City: SEATTLE Zip Code: 98108 County: King
Latitude: 47.53164 Longitude: -122.32877 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 24N 4E 32

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
GLITSA LUST	Upland	Cleanup Started	NW	Northwest Region	Independent Action
Glitsa Paint Drums	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	C					
Metals - Other	C					
Non-Halogenated Solvents	C					
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/2/1992
LUST - Report Received	Completed		8/6/2009
Site Discovery/Release Report Received	Completed		2/24/2010
Non-LUST Ind Report Received	Completed		5/10/2010
LUST - Report Received	Completed		6/24/2010
LUST - Report Received	Completed		7/7/2010

Cleanup Site Details

Cleanup Site ID: 9951

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/12/2011
Site Hazard Assessment	Completed	5/23/2014	6/3/2015
Hazardous Sites Listing	Completed		7/1/2015
VCP Receipt of Plan or Report	Completed		12/8/2020
LUST - Report Received	Completed		12/8/2020
VCP Receipt of Plan or Report	Completed		12/8/2020
VCP Opinion on Site Cleanup	Completed	12/8/2020	2/3/2021
SHARP Assessment	Completed		2/14/2025