

Cleanup Site Details

Cleanup Site ID: 9951
Cleanup Site ID: 9951 **Facility/Site ID:** 63168342 **UST ID:** 6178 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Glitsa American Inc [Glossary](#)
Alternate Names: GLITSA AMERICAN, Glitsa American Inc, GLITSA AMERICAN INCORPORATED, Tenor Co

LOCATION
Address: 327 S KENYON ST **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.53164 **Longitude:** -122.32877 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 32

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
GLITSA LUST	Upland	Cleanup Started	NW	Northwest Region	Independent Action
Glitsa Paint Drums	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	C					
Metals - Other	C					
Non-Halogenated Solvents	C					
Petroleum-Gasoline	C	C				

Key:

B - Below Cleanup Level	C - Confirmed Above Cleanup Level	RA - Remediated-Above
S - Suspected	R - Remediated	RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/2/1992
LUST - Report Received	Completed		8/6/2009
Site Discovery/Release Report Received	Completed		2/24/2010
Non-LUST Ind Report Received	Completed		5/10/2010
LUST - Report Received	Completed		6/24/2010
LUST - Report Received	Completed		7/7/2010

Cleanup Site Details

Cleanup Site ID: 9951

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/12/2011
Site Hazard Assessment/Federal Site Inspection	Completed	5/23/2014	6/3/2015
Hazardous Sites Listing/NPL	Completed		7/1/2015
VCP Receipt of Plan or Report	Completed		12/8/2020
LUST - Report Received	Completed		12/8/2020
VCP Receipt of Plan or Report	Completed		12/8/2020
VCP Opinion on Site Cleanup	Completed	12/8/2020	2/3/2021