

## Underground Storage Tank System Summary

Stat	e of Washingto									
Site Nam	e: SU	N COUNTI	RY GRAIN	CORP					Glossary	
UST ID:	1559	Fac	ility/Site ID:	74176252		Latitude:	46.75425	Active Tag(s):	N/A	
Address:	PO BO	X 306/BRUCE	SIDING			Longitude:	-119.04976	Responsible U	nit: Eastern	
	OTHELLO, WA 99344				County:	Adams				
Tank Sur	nmary									
Tank Name		Tank Status			Tank Install Date					
1		Closed in Place			12/31/1964					
Tank Name:		1			Tank Status: Closed in Place					
Tank Installation:		12/31/1964	/31/1964 Tank Upgrade:			Business License Endorsement Expiration:				
Tank Status	s Date:	8/6/1996	Piping Ins	tallation:		Tank Per	manently Clos	ed Date:		
Tank Information							Piping Information			
Material: Steel					Material:	Material:				
Construction:						Construc	Construction:			
Corrosion Protection:						Corrosio	Corrosion Protection:			
Manifolded Tank:						SFC* at 1	SFC* at Tank:			
Release Detection:						SFC* at [	SFC* at Dispenser/Pump:			
Tank Manufacturer:						Primary I	Primary Release Detection:			
Spill Prevention:						Seconda	Secondary Release Detection:			
Overfill Prevention:						Pumping	Pumping System:			
Actual Capacity:						Piping Manufacturer:				
Capacity Range:						*SFC = S	*SFC = Steel Flex Connector			
Compartment Substance Stored				Substand	Substance Used Capacity					