

INCIDENT DETAIL REPORT

01/19/2016

INITIAL REPORT:

INCIDENT#: 86372

Incident Info:

Incident Date: 01/11/2016 **Incident#:** 86372 **ERTS#:** 662096
Report Date: 1/11/2016 1:05:00 PM **Incident Category:** Oil Spill
Received By **Official Notification?** N **After Hour?** N

Caller:

Name: NICK FRANTSEVICH **Street Address:**
Org/Bus. Name: GREENBUILD DEVELOPMENT **Other Address:**
Phone# (253) 269-2748 **Ext. Ref#** **City, State, Zip:** WA
Email: **Is Caller Resp?** N **Confidential?** N

Location:

Location: **LAT:** **LONG:**
Street Address: 2024 NW 62ND ST **Driving**
Other Address: **Direction:**
City, State, Zip: SEATTLE, WA
County: KING **Region:** NWRO

What's happened:

OIL:

Vessel/Facility	Source	Other Source	Vessel IMO#	Reg?	Pri?
	Underground Storage Tank			N	Y

Material	Other Material	Medium	Other Medium	Spill Qty	Unit	Rec. Qty
DIESEL/MARINE GAS OIL		Land		100.00	Gals	

Activity: CONSTRUCTION **Impact:** SOIL CONTAMINATION
Other Activity: **Does Not Effect WA:** N

PRP:

Contact Name	Entity Name	Phone Number	Email Address	Street Address	Pri?
NICK FRANTSEVICH	GREENBUILD DEVELOPMENT			SEATTLE, WA	N

Referral:

Name	Org. Name	Ref. Method	Ref. Date	Phone Number	Email Address	Pri?
Laura Hayes	SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE	E-MAIL ATTACHMENT	01/11/16	(425) 649-7085	lhay461@ecy.wa.gov;4254952632@OnPage.com	Y

INCIDENT DETAIL REPORT

01/19/2016

DONNA K MUSA TCP	TOXICS CLEANUP	E-MAIL ATTACHMENT	01/11/16	(425) 649-7136	DMUS461@ECY.WA.GOV	N
ERIC AUTRY SEATTLE PUBLIC UTIL WQ	SEATTLE	E-MAIL ATTACHMENT	01/11/16	(206) 684-7988	Email Seattle WQ	N

Initial Info:

CALLER REPORTS AN UNDERGROUND STORAGE TANK WAS BROUGHT TO THE SURFACE THROUGH CONSTRUCTION DEMO WORK --TIPPED OVER AND SPILLED APPROXIMATELY 100 GALLONS OF DIESEL ONTO SOIL. THE BUILDING INSPECTOR WHO WAS ON SITE AT THE TIME PLACED A STOP WORK ORDER ON THE JOB UNTIL THE CONTAMINATION IS CLEANED UP. CURRENTLY THEY ARE USING CAT LITTER TO ABSORB AS MUCH OIL AS POSSIBLE.

Incident Info:

Incident Date: 01/11/2016
Report Date: 1/11/2016 1:05:00 PM
Received By:
Incident#: 86372
Incident Category: Oil Spill
Official Notification? N
ERTS#: 662096
After Hour? N

Caller:

Name: JAMES FACKLER
Org/Bus. Name: CITY OF SEATTLE
Phone# (206) 363-3211 **Ext. Ref#**
Email: James.Fackler@seattle.gov
Street Address:
Other Address:
City, State, Zip: WA
Is Caller Resp? N **Confidential?** N

Location:

Location:
Street Address: 2024 NW 62ND ST
Other Address:
City, State, Zip: SEATTLE, WA
County: KING **Region:** NWRO
LAT:
Driving Direction:
LONG:

What's happened:

OIL:

Vessel/Facility	Source	Other Source	Vessel IMO#	Reg?	Pri?
	Underground Storage Tank			N	Y

Material	Other Material	Medium	Other Medium	Spill Qty	Unit	Rec. Qty
Heating Oil		Land		250.00	Gals	

Activity: CONSTRUCTION
Other Activity:
Impact: SOIL CONTAMINATION
Does Not Effect WA: N

PRP:

Contact Name	Entity Name	Phone Number	Email Address	Street Address	Pri?
BATALY AFISHUK				PO BOX 24810 FEDERAL WAY, WA	Y

INCIDENT DETAIL REPORT

01/19/2016

Referral:

Name	Org. Name	Ref. Method	Ref. Date	Phone Number	Email Address	Pri?
Laura Hayes	SPILLS, PREVENTION, PREPAREDNESS AND RESPONSE	E-MAIL ATTACHMENT	01/11/16	(425) 649-7085	lhay461@ecy.wa.gov;4254952632@OnPage.com	Y
DONNA K MUSA TCP	TOXICS CLEANUP	E-MAIL ATTACHMENT	01/11/16	(425) 649-7136	DMUS461@ECY.WA.GOV	N
ERIC AUTRY SEATTLE PUBLIC UTIL WQ	SEATTLE	E-MAIL ATTACHMENT	01/11/16	(206) 684-7988	Email Seattle WQ	N

Initial Info:

REPORT TAKEN AT FRONT DESK SIMULTANEOUSLY WHILE REPORTING PARTY FROM FIRST REPORT WAS ON THE PHONE WITH ERTS COORDINATOR. SOME INFORMATION IS CONFLICTING, INCLUDING THE MATERIAL SPILLED AND THE QUANTITY SPILLED.

REPORT NOTES:

CITY OF SEATTLE INSPECTOR REPORTED THAT A HEATING STORAGE TANK WAS DAMAGED BY EXCAVATOR DURING ITS REMOVAL. LEAK STARTED AROUND 12:00M, FIRE DEPARTMENT TRIED TO PLUG HOLES, BUT THERE IS A HUGE AMOUNT OF SOIL IMPACTED.

INCIDENT DETAIL REPORT

01/19/2016

FOLLOW-UP REPORT:

INCIDENT#: 86372

Incident Info:

Case Name Greenbuild UST Failure

Incident#: 86372

ERTS#: 662096

Incident Date: 01/11/2016

ANT#:

SIC#:

Inc. Category: Oil Spill

PREP Vsl Emerg? N

Tug Deployment? N

Inc. Type#: 5

Status: Closed

Potential Enf.? N

ECY Hired Contractor? N

Location:

Location:

LAT: 47.67

LONG: -122.38

Street Address: 2024 NW 62ND ST

Driving
Direction:

Other Address:

City, State, Zip SEATTLE, WA

County: KING

Region: NWRO

Response:

Name	Role	Action	Start Date	End Date	Overtime?
CHAD SCHWATKA	SOSC	FIELD RESPONSE - INVESTIGATION	01/12/16	01/12/16	N

What's happened:

OIL:

Vessel/Facility	Source	Other Source	Vessel IMO#	Reg?	Pri?	Delvr/Recvr
	Underground Storage Tank			N	Y	

Material	Other Material	Medium	Other Medium	Spill Qty	Unit	Rec. Qty	Rec. 24Hrs
Heating Oil		Land		250.00	Gals		

Cause:

Cause	Other Cause	Immediate?	Remarks
INEXPERIENCE		N	

Activity: CONSTRUCTION

Impact: SOIL CONTAMINATION

Other Activity:

Does Not Effect WA: N

Weather & Tracking:

Weather:

Wind Speed:

Tide Stage:

Visibility:

Wind Direction:

Tide Height:

Water Temp.

Current:

Swell Height:

Temperature:

Wave Height:

Swell Direction:

INCIDENT DETAIL REPORT

01/19/2016

Sample Taken? N

Entry By: Chad Schwatka

Photo Taken? N

Lab Analysis? N

Entry Date: 01/19/2016

PIO Involved? N

Document? N

Update By:

Press Release? N

Interview? N

Last Update:

PRP:

Contact Name	Entity Name	Phone Number	Email Address	Street Address	Pri?
BATALY AFISHUK				PO BOX 24810 FEDERAL WAY, WA	Y

Notification:

***No Notification Info.

***No TRAP Info.

Narrative:

Name: CHAD SCHWATKA

Last Update: 1/19/2016 10:59:45 AM

CS and AQ responded to site to confirm some action was being taken to cleanup standing product and remove the threat of a discharge to surface water. Onsite ~ 12:40 01/12/2015. 2 large standing puddles of product still existed on site amidst mud and rip rap rock. Product was fairly well contained and showed no ability to leave the site and reach surface waters or storm systems. Referred to TCP for follow up. NFA from NWRO Spills.