



Water Quality Program

Permit Submittal Electronic Certification

Permittee: SKAGIT COUNTY SEWER DIST 2 BIG LAKE WWTP

Permit Number: WA0030597

Site Address: 17079 STATE ROUTE 9
Mount Vernon, WA 98274

Submittal Name: Reporting Permit Violations Written Report

Version: 1

Due Date:

Comments: On Friday July 5, 2019 at 10:30am I was called about a manhole leaking at Zoya Dr. & Lakeview Blvd. I found that the manhole was overflowing to the catch basin on the corner of Lakeview and Zoya. I immediately called Bayside Services to have them clear the line. The line was plugged with sticks that were put down pick holes of manhole cover on Zoya Dr. We cleared the line and vactored out catch basin, this was completed by 12:30pm. We will send out a PSA with billing, requesting owners to not put anything in manholes. We will continue to monitor the line for back ups. I estimate the amount leaked to the catch basin is between 2 to 3 hundred gallons.

I certify under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Kelly Wynn

7/10/2019 8:55:27 AM

Signature

Date