



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

August 15, 2018

Mr. Kevin Manzano
Cowlitz Clean Sweep
55 International Way
Longview, WA 98632

Re: NPDES Permit Number CNE004613

Dear Mr. Manzano:

Enclosed is the report from the Department of Ecology's recent Industrial Stormwater NPDES General Permit compliance inspection conducted at your facility on July 24, 2018. I would like to thank your staff for the time they spent with me during my visit.

Please contact me at kevin.hancock@ecy.wa.gov or (360) 407-6298 if you have any questions, comments or would like additional technical assistance.

Sincerely,

Kevin Hancock
Industrial Stormwater Facility Manager
Southwest Regional Office
Water Quality Program

Enclosures: Industrial Stormwater Inspection Report
Photo Log

cc: Charles Gilman, Ecology
Clay Keown, Ecology



Photo 1 of 6: The office entrance.



Photo 2 of 6: Employee and customer parking. There is no production in this area.



Photo 3 of 6: They store vehicles in the production area. The vehicles were not leaking.



Photo 4 of 6: Chemicals are stored in a covered contained area.



Photo 5 of 6: These two barrels of cleaning fluid are stored outside without containment. They were not leaking.



Photo 6 of 6: There is gear stored outside. They are in covered containment.

