



STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

1250 West Alder Street • Union Gap, Washington 98903-0009 • (509) 575-2490

April 10, 2020

Dave Piepel  
Piepel Land Holdings  
1110 S. Webb Place  
East Wenatchee, WA 98802

**RE: Discharge Monitoring Reports for Piepel Land Holdings, Piepel Premium Fruit Storage--WAG435289 and Piepel Premium Fruit Packing—WAG994308**

Dear Dave Piepel:

Ecology has reviewed your 2019 annual discharge monitoring reports (DMR's). The tables below summarize the permit violations found. The purpose of this letter is to provide you an opportunity to review these violations and submit corrections if the records are not accurate.

**WAG435289—Piepel Premium Fruit Storage (Chehalis Street)**

Outfall No(s).	Parameter	Date	Reported Value	Permit Limit
001	Total Residual Chlorine (TRC), mg/L (incorrect sampling)	06/24/2019 06/24/2019	5.3 5.3	0.5
001	pH, standard units (SU)	10/28/2019	5.95	6.00-9.00
002	TRC, mg/L	06/24/2019	2.80	0.5

**WAG994308—Piepel Premium Fruit Packing (Webb Street)**

Outfall No(s).	Parameter	Date	Reported Value	Permit Limit
002	Biochemical Oxygen Demand (BOD), mg/L	10/28/2019 10/28/2019	174 174	100

Other than reporting any errors on the tables above, no further response is required from your facility. If you have any questions or concerns please contact me at 509-454-7864, or email [marcia.porter@ecy.wa.gov](mailto:marcia.porter@ecy.wa.gov).

Sincerely,

*Marcia Porter*

Marcia Porter  
General Permit Manager  
Water Quality Program

cc: Tony Walton—Piepel Land Holdings, [tony@premiumharvest.com](mailto:tony@premiumharvest.com)