



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

*PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341*

April 3, 2020

Tony White
Woods Logging Supply, Inc.
PO Box K
Longview, WA 98632

Re: NPDES Permit Number WAR010300

Dear Tony White:

Enclosed is the report from the Department of Ecology's recent Industrial Stormwater NPDES General Permit compliance inspection conducted at your facility on March 4, 2020. I would like to thank you for the time you spent with me during my visit.

Please contact me at Kevin.Hancock@ecy.wa.gov or (360) 407-6298 if you have any questions, comments, or would like additional technical assistance.

Sincerely,

A handwritten signature in blue ink, appearing to read "Kevin Hancock", is written over a horizontal line.

Kevin Hancock
Water Quality Permit Manager
Southwest Regional Office
Water Quality Program

Enclosures: Industrial Stormwater Inspection Report
Photolog

cc: Charles Gilman, Ecology
Joyce Smith, Ecology



Water Compliance Inspection Report

Section A: National Data System Coding (i.e., PCS)

Transaction Cod 1 <u>N</u> <u>5</u>	NPDES <u>W</u> <u>A</u> <u>R01</u> <u>0300</u>	yr/mo/dy <u>2020</u> <u>03</u> <u>04</u>	Inspection Type <u>0</u> <u>C</u> <u>S</u>	Inspector <u>2</u> <u>1</u> <u>1</u>	Facility Type
Remarks 21 66					
Inspection Work Days 67 <u>1</u> <u>1</u> <u>1</u> 69	Facility Self-Monitoring Evaluation Rating 70 <u>1</u>		B1 71 <u>1</u>	QA 72 <u>1</u>	Reserved 73 <u>1</u> <u>1</u> 74 75 <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> <u>1</u> 80

Section B: Facility Data

Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Woods Logging Supply, Inc. 702 Industrial Way Longview, WA 98632	Entry Time/Date 09:00 hrs 3/4/2020	Permit Effective Date January 1, 2020
	Exit Time/Date 09:45 hrs 3/4/2020	Permit Expiration Date December 31, 2024
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number Tony White Branch Manager Phone: (360) 577-8030 Fax: (360) 423-7567 Cell: (360) 957-2050 E-mail: tony@woodslogging.com	Other Facility Data (e.g., SIC NAICS, and other description information) This facility is 3.3-acre retail and wholesale logging equipment supplier. Their business hours are 6:00 a.m. to 6:00 p.m. Monday – Friday, and 7:30 a.m. to 1:00 p.m. on Saturdays. Standard Industry Code (SIC): 0851, Forestry Services, 5085, Industrial Supplies; North American Industry Classification System (NAICS): 115310, Support Activities for Forestry, 423840, Industrial Supplies Wholesale Merchandiser.	
Name, Address of Responsible Official/Title/Phone and Fax Number <div>Contacted <input type="checkbox"/> Yes <input type="checkbox"/> No</div>		

Section C: Areas Evaluated During Inspection (Check only those areas evaluated)

<input checked="" type="checkbox"/> Permit	<input checked="" type="checkbox"/> Self-Monitoring Program	<input type="checkbox"/> Pretreatment	<input type="checkbox"/> MS4
<input checked="" type="checkbox"/> Records/Reports	<input checked="" type="checkbox"/> Compliance Schedules	<input type="checkbox"/> Pollution Prevention	
<input checked="" type="checkbox"/> Facility Site Review	<input checked="" type="checkbox"/> Laboratory	<input checked="" type="checkbox"/> Stormwater	
<input type="checkbox"/> Effluent/Receiving Waters	<input checked="" type="checkbox"/> Operations & Maintenance	<input type="checkbox"/> Combined Sewer Overflow	
<input type="checkbox"/> Flow Measurement	<input type="checkbox"/> Sludge Handling/Disposal	<input type="checkbox"/> Sanitary Sewer Overflow	

Section D: Summary of Findings/Comments

(Attach additional sheets of narrative and checklists, including Single Event Violation codes, as necessary)

The facility submitted a Notice of Termination (NOT) of their Industrial Stormwater General Permit (ISGP). The inspection was performed to determine if the site meets the conditions in section 13, page 31 of the ISGP, and can be terminated.

In 2008 the facility was determined by the Department of Ecology (Ecology) to be a Significant Contributor to Pollutants (SCOP) to waters of the state, and required to seek stormwater discharge authority under the ISGP. Stormwater sampling placed the site in a Corrective Action Level 3 for zinc. As a response they replaced the roof. Since the roof was replaced the facility has not recorded an exceedance of a benchmark.

The inspection determined the facility is no longer a SCOP, and the ISGP can be terminated according to permit condition S13 on page 43:

- Ecology may approve a NOT request when the Permittee meets one or more of the following conditions, and Ecology determines that the discharges from the facility are no longer required to be covered under this permit.

Verify Latitude and Longitude

Door: N 46.11601° W -122.93321°
Outfall: N 46.11603° W -122.93365°

☐ Announced ☒ Unannounced

Name and Signature of Inspector Kevin P. Hancock	Agency/ Office Number Ecology/SWRO (360) 407-6298	Date: April 3, 2020
Signature of Management QA Reviewer Steve Eberl	Agency/ Office Number Ecology/SWRO (360) 407-6293	Date: April 3, 2020

Photo 1 of 6: This is the entrance, and public parking.



Photo 2 of 6: Stormwater is routed to one outfall. This is the sampling location.



Photo 3 of 6: Product is stored under cover, and exposed to stormwater. The cables are designed for outside use.



Photo 4 of 6: Cable fabrication is done inside this fabrication shop.



Photo 5 of 6: A portion of the facility is gravel. They store product in the gravel areas.



Photo 6 of 6: Their fueling area is covered with secondary containment.

