



Water Quality Program

Permit Submittal Electronic Certification

Permittee: Double M Enterprises Blockhouse Butte Pit

Permit Number: WAG505214

Site Address: 1180 HWY 142
GOLDENDALE, WA 98620

Submittal Name: Production and Operating Status Verification Report

Version: 1

Due Date: 1/30/2023

Questionnaire

Number	Permit Section	Question	Answer
1	S10.B	Permit Number	WAG505214
2	S10.B	Company Name	Double M Enterprises
3	S10.B	Site Name	Double M Enterprises Blockhouse Butte Pit
4	S10.B	Billing Contact's First and Last Name	Mark Ruiter
5	S10.B	Billing Contact's Mailing Address	869 E Badger Road, Lynden, WA, 98264
6	S10.B	Billing Contact's Phone Number	360-354-2271
7	S10.B	Billing Contact's Email Address	mark@martinsfeed.com
8	S10.B	Is this facility permitted for mining, screening, washing?	Yes
8a	S10.B	Did this facility operate 90 calendar days or more annually for the previous calendar year?	No
8b	S10.B	Is this a portable mining, screening, washing operation?	No
9	S10.B	Is this facility permitted for concrete production and / or concrete recycling?	No
10	S10.B	Is this facility permitted for asphalt production and / or asphalt recycling?	No

I certify under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Kim Ninnemann

2/2/2023 8:43:20 AM

Signature

Date