



STORMWATER COMPLIANCE INSPECTION REPORT

State of Washington Department of Ecology
15700 Dayton Ave N. Shoreline, WA 98133-9716

WADOE Stormwater
Compliance Inspection Form

Phone: (425) 649-7000
FAX: (425) 649-7098

Section A: General Data

Inspection Date 3/8/2023	Permit # WAR309090	County King	Receiving Waters MS4	Inspector(s) Luis Buen Abad	Facility Type Construction
Discharges to: Surface Water <input checked="" type="checkbox"/> Ground Water <input type="checkbox"/>					

Section B: Facility Data

Name and Location of Construction Site Inspected		Entry Time	Exit Time									
Water Quality Name: Mt. Baker Properties MLK Jr Facility Site Name: Phillips 66 070644 2800 Martin Luther King Jr Way S Seattle, WA 98144		10:30 AM	11:25 AM									
Site Contact		Additional Participants:										
Owen Reese, P Principal Water Resources Engineer Direct: 206.838.5844 Cell: 206.491.9327 Aspect Consulting LLC 710 2nd Ave, Suite 550, Seattle, WA 98104		<table border="0"> <tr> <td></td> <td>Yes</td> <td>No</td> </tr> <tr> <td>Samples Taken?</td> <td><input type="checkbox"/></td> <td><input checked="" type="checkbox"/></td> </tr> <tr> <td>Photos Taken?</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>			Yes	No	Samples Taken?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Photos Taken?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Yes			No								
Samples Taken?	<input type="checkbox"/>			<input checked="" type="checkbox"/>								
Photos Taken?	<input checked="" type="checkbox"/>	<input type="checkbox"/>										
Responsible Official(s):												
David Tan Executive Diredctor david@mtbakerhousing.org 2916 S McClellan St Seattle WA, 98144-5502	Phone:											
Phone: (206) 725-4152	Phone:											

Section C: Summary of Findings/Comments

BACKGROUND

This site is covered under the Construction Stormwater General Permit. The purpose of this inspection was to conduct a compliance inspection and to provide technical assistance as appropriate.

INSPECTION

All construction activities have ceased. The site is stabilized and BMPs removed.

Section D: Compliance

Permit is approved for termination.

E-SIGNATURE

LUIS BUEN ABAD

Luis Buen Abad
Date: 3/14/2023
Water Quality Environmental Specialist
WA Department of Ecology

INSPECTION PHOTO LOG
MT BAKER PROPERTIES WAR309090
PHOTOS BY LUIS BUEN ABAD
3/8/2023



PHOTO 1 SITE STABILIZED



PHOTO 2 SITE STABILIZED



PHOTO 3 SITE STABILIZED



PHOTO 4 SITE STABILIZED