



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY
CENTRAL REGIONAL OFFICE
WATER COMPLIANCE INSPECTION REPORT

substitute for OMB
No. 2040-0057
and EPA form 3560-3
(Rev. 9-94)
(last file update 12-95)

FACILITY NAME: MONSON BULK CRUSH FACILITY

FACILITY NUMBER: ST0009266

SECTION 1: INSPECTION INFORMATION

START DATE: 6/15/2022

PRIMARY INSPECTOR MATTHEW DURKEE

INSPECTION TYPE (CHECK ONE):

- COMPLIANCE INSPECTION W/O SAMPLING ☒
COMPLIANCE INSPECTION W/ SAMPLING ☐
COVERAGE INSPECTION ☐
COMPLIANCE FOLLOW-UP INSPECTION ☐
TECHNICAL ASSISTANCE VISIT ☐
OPERATION & MAINTENANCE INSPECTION ☐

PERMIT # ST0009266
COMPLAINT # _____
LAB PROJECT # _____
ENFORCEMENT DOCKET # _____
Y/N: Y
Scheduled _____
ANNOUNCED _____
PART OF A GROUP _____

REASON FOR INSPECTION
(CHECK ONE)

FAC. REP

- ROUTINE ☒
COMPLAINT ☐
DRIVE BY ☐
ENFORCEMENT ☐
QA ☐
BIO-MONITORING ☐
OTHER (SPECIFY) ☐

PARTICIPANTS

MATT DURKEE
CALEB BOS
STEPHANIE GIESEN
CHRISTIAN NANCE

AGENCY

ECOLOGY
ECOLOGY
ECOLOGY
GOOSE RIDGE

(Y/N)

N
N
N
Y

PHONE #

(509) 379-4384
(509) 426-6079
(509) 379-3878
(206) 972-9998

SECTION 2: FACILITY INFORMATION

SECTION 3: AREAS EVALUATED DURING INSPECTION

FACILITY: MONSON BULK CRUSH FACILITY

NAME: (GOOSE RIDGE WINERY)

ADDRESS: 63615 E JACOBS ROAD,
BENTON CITY, WA 99320

DATE TIME

ENTRY 1 6/15/22 10:00 AM

EXIT 1 6/15/22 12:30 PM

ENTRY 2

EXIT 2

ENTRY 3

EXIT 3

ENTRY TYPE
(CHECK ONE)

- DENY ☐
DELAY ☐
WARRANT ☐
REGULAR ☒

N = NOT EVALUATED, S = SATISFACTORY
M = MARGINAL, U = UNSATISFACTORY

INSPECT BENCH SHEETS N
INSPECT PERMIT N
RECORDS/REPORTS N
FLOW MEASUREMENTS S
LABORATORY N
EFFLUENT/RECEIVING WATER S

PRE-TREATMENT S
COMPLIANCE SCHEDULES N
SELF MONITORING PROGRAM S
OPERATION & MAINTENANCE S
SLUDGE DISPOSAL N
FACILITY SITE REVIEW N
LAB ACCREDITATION N

OTHER (SPECIFY) _____

SECTION 4: SUMMARY OF FINDINGS / COMMENTS (ATTACH ADDITION PAGES IF NEEDED)

ECOLOGY STAFF TOURED THE FACILITY STARTING WITH THE TWO DOUBLE LINED WASTEWATER LAGOONS. GOOSE RIDGE WINERY (MONSON BULK CRUSH IN PARIS) HAD RECENTLY INSTALLED TALL MESH NETTING AROUND THE LAGOONS TO CAPTURE WINDBLOWN WASTEWATER DROPLETS FROM THE EVAPORATORS. THE LAGOONS HAVE BEEN AT CAPACITY AND THERE HAVE BEEN ISSUES WITH WASTEWATER MIST FROM THE EVAPORATORS BLOWING AWAY FROM THE LAGOONS AND COATING THE ADJACENT VINEYARDS AND GROUND WITH PURPLE RESIDUE. ALSO OBSERVED SOME EROSIONAL ISSUE ADJACENT TO THE LAGOONS ASSOCIATED WITH STORMWATER RUNOFF FROM THE FACILITY. THE TOUR PROCEEDED INSIDE THE WINERY BUILDINGS AND INCLUDED WINE BARREL STORAGE AREAS AND AUTOMATED BARREL WASHING EQUIPMENT THAT PRODUCES SOME OF THE WASTEWATER FROM THE FACILITY.

AFTER THE TOUR OF THE FACILITY ECOLOGY STAFF AND CHRISTIAN NANCE MET TO DISCUSS THE ONGOING VIOLATIONS RELATED TO THE LACK OF LAGOON CAPACITY AND PAPERWORK DISCREPANCY THAT HAS RESULTED IN THE LAGOON INFLUENT VIOLATIONS. POSSIBLE FUTURE WASTEWATER DISCHARGE ALTERNATIVES WERE DISCUSSED. GOOSE RIDGE WINERY IS CONSIDERING REPLACING THE EXISTING LAGOONS WITH LARGER LAGOONS AND POTENTIALLY LAND TREATMENT DEPENDING ON THE CAPACITIES. ECOLOGY STAFF OUTLINED THE NECESSARY DOCUMENTATION AND REQUIREMENTS GOOSE RIDGE WINERY WILL NEED TO MEET FOR THE FUTURE WASTEWATER IMPROVEMENTS AT THE FACILITY.



SECTION 5: FOLLOW-UP (CHECK ALL THAT APPLY)

TYPE	DETAIL	RESP. PERSON	SCHEDULE	DONE
<input type="checkbox"/> CONDUCT CLASS II	_____	_____	_____	_____
<input type="checkbox"/> LAB ACCRED MANUAL	_____	_____	_____	_____
<input type="checkbox"/> RE-INSPECT	_____	_____	_____	_____
<input type="checkbox"/> RE-OPEN PERMIT	_____	_____	_____	_____
<input type="checkbox"/> SEND APPLICATION	_____	_____	_____	_____
<input type="checkbox"/> TECH ASSIST-REGULAR	_____	_____	_____	_____
<input type="checkbox"/> TECH ASSIST-OUTREACH	_____	_____	_____	_____
<input type="checkbox"/> MOD PERMIT AT RENEWAL	_____	_____	_____	_____
<input type="checkbox"/> FACILITY ACTION	_____	_____	_____	_____
<input type="checkbox"/> ENFORCEMENT (WARN LET	_____	_____	_____	_____
<input type="checkbox"/> NOV, ORDER, PENALTY)	_____	_____	_____	_____
<input type="checkbox"/> OTHER (SPECIFY)	_____	_____	_____	_____

SECTION 6: ACTIVITIES (CHECK ALL THAT APPLY)

DESCRIPTION	DATE COMPLETED	TRACKING NUMBER
<input type="checkbox"/> DATA RECEIVED FROM LAB	_____	_____
<input type="checkbox"/> DRAFT INSPECTION REPORT COMPLETED	_____	_____
<input type="checkbox"/> FINAL INSPECTION REPORT COMPLETED	_____	_____
<input type="checkbox"/> FINAL INSPECTION RPT RCD FROM EILS	_____	_____
<input type="checkbox"/> FORM 3506 SENT TO EPA	_____	_____
<input type="checkbox"/> INSPECTION REPORT REVIEWED	_____	_____
<input type="checkbox"/> SAMPLES TO LAB	_____	_____
<input type="checkbox"/> OTHER	_____	_____

SECTION 7: SIGNATURES

NAME (PRINT)	SIGNATURE	DATE	AGENCY/PH#
INSPECTOR 1 MATTHEW DURKEE, LHG		1/12/24	(509) 379-4384
INSPECTOR 2			
REVIEWER ERIK VAN DOREN		1/17/2024	509-571-0934

SECTION 8: APPENDIX - PHOTOGRAPHS



Photo 1. Wastewater lagoons.



Photo 2. Outside of Goose Ridge Winery.



Photo 3. Wastewater lagoons.




Photo 4. View from inside of facility to open garage door.