

PHOTO ADDENDUM – COLUMBIA DISTRIBUTING



001
Description: Photo showing northwest corner of rear lot. Dumpsters, shed, and miscellaneous storage are in this area.



002
Description: Photo showing west fence line of rear lot. Miscellaneous storage of pallets and kegs in this area.

PHOTO ADDENDUM – COLUMBIA DISTRIBUTING



003
Description: Photo northwest corner of rear lot with vehicles and miscellaneous storage.



004
Description: Photo showing inside bay door with spill kit present.



005

Description: Photo showing inside bay door. Storage of spill kit materials and DEF fluids on secondary containment.




006

Description: Photo showing new sample point location in planter bed on the southeast corner of the building.

PHOTO ADDENDUM – COLUMBIA DISTRIBUTING



007
Description: Photo showing vault of the new sample point location.



008
Description: Photo showing facility site map.

PAGE INTENTIONALLY LEFT BLANK