



# Permit Compliance Inspection Report

## Water Quality Program

Central Region Office

### A. General Information

Facility Name & Address: Cowiche City Road Plant  
200 Cowiche City Road, Cowiche, WA 98923

Permit Type: Fruit Packer General Permit Permit Number: WAG435106

Permit Effective Dates: 01/01/2022 to 12/31/2026

Date(s) of Inspection: 04/09/2024

Inspection Duration: 09:00 AM to 11:00 AM

Discharge to: POTW and Ground Water

Type of Inspection: Announced  
Compliance Inspection - Without Sampling

Weather: partly cloudy 53 °F

Photographs Taken:  Yes  No Samples Taken:  Yes  No

### B. Personnel Information

Ecology Representative(s): Marcia Porter

Facility Representative(s): Barb Evans  
Regulatory/RMP Manager  
Phone:509-830-7367 Email:barbie1evans@gmail.com

Responsible Party/Official: Mrs. Jeanette Evans  
P.O. Box 70  
Cowiche, WA 98923-0070  
Phone:509-678-4127 Email:jevans@evansfruitco.com

Inspector Signature(s)

*Marcia Porter*

4/11/2024

Marcia Porter

Environmental Specialist 4

Date

Reviewer Signature

*Andrea Jedel*

Andrea Jedel

Industrial Unit Supervisor

4/14/2024

### C. Facility Description & Background

This facility has been continuously permitted under the Fresh Fruit Packing General Permit since the inception of the general permit in 1994. They have had relatively few problems over the years. The facility is currently being well operated and managed under new administrative management.

## D. Inspection Narrative & Observations

### 1. Permit Documentation and Records Review

At the time of the inspection, the records review were complete, were up-to-date and in compliance with the general permit requirements.

### 2. Site Walkthrough

At the time of the inspection the facility was exceptionally clean and well operated. There were no violations of permit requirements viewed. The facility has upgraded their engine rooms associated with the CA Storage making them more efficient in operation.

## E. Corrective Actions Required for Compliance

At the time of the inspection, none for this facility. This facility would like to land apply wastewater discharges from the lined evaporative lagoon in a substantial sized field directly behind the lagoon. I sent them a modification of permit coverage form via email. Upon viewing at the time of the inspection, I did not see an issue with this proposed modification to their coverage.


We did discuss some discrepancies at one of the Evans Fruit Storage facilities in ERO. I had noticed (as the statewide permit manager) an issue with their reporting with incorrect use of the M code for parameters that required monitoring. Barb said she would begin working with the lab and staff at the Far West facility to correct that error and monitor the correct parameters for hydrocooler use during cherry season beginning this year.

If you have any questions or concerns regarding this inspection report, please contact [Marcia Porter](mailto:marcia.porter@ecy.wa.gov) at 509-406-6624 or [marcia.porter@ecy.wa.gov](mailto:marcia.porter@ecy.wa.gov).

## ADA Accessibility

The Department of Ecology is committed to providing people with disabilities access to information and services by meeting or exceeding the requirements of the Americans with Disabilities Act (ADA), Section 504 and 508 of the Rehabilitation Act, and Washington State Policy #188.

To request an ADA accommodation, contact Ecology by phone at 360-407-6831 or email at [ecyadacoordinator@ecy.wa.gov](mailto:ecyadacoordinator@ecy.wa.gov). For Washington Relay Service or TTY call 711 or 877-833-6341. Visit [Ecology's website](#) for more information



**Photo 1**

**Description:** *Evans Fruit*

**Photo 2**

**Description:** Float water being filtered from leaves and debris that comes in with the fruit. Debris is collected and disposed of as solid waste.



**Photo 3**

**Description:** *pack line is kept very clean underneath*



**Photo 4**

**Description:** *chemical usage on the line for fruit cleaning, disinfection, and polishing (aesthetics)*



**Photo 5**

**Description:** *Discharge to POTW (open line) and the plugged line to the evaporative lagoon. With a modification to cover the POTW line will be plugged and the line to the evaporative lagoon will be unplugged.*



**Photo 6**

**Description:** proper storage of cull and/or rot product for pickup. Lined bins that contain all product and liquid



**Photo 7**

**Description: Lined evaporative lagoon. Facility will get aerators going before using for when the modification of coverage is completed.**



**Photo 8**

**Description: property for land application with sprinklers. Runs from back of lined lagoon to the house in the distance. Acreage available will be listed on the change of operations modification form.**