

**ERTS # 640183**

## Initial Report

**External Reference #**

### Caller Information

**First Name** MICHAEL  
**Last Name** BOWHAY  
**Business Name** DAYTON WWTP  
**Street Address**  
**Other Address**  
**City** DAYTON (COLU **State** WA **Zip**  
**E-mail** WWTPDAYTON@HOTMAIL.CO **Confidential\_FL** ☐  
**Phone** (509) 382-2937 **Ext** **Type** Business

### Where did it happen

**Berth**  
**Location Name** DAYTON WWTP  
**Street Address** 800 STOCKTON RD  
**Other Address**  
**City/Place** DAYTON (COLUMBI **State** WA **Zip**  
**County - Region** COLUMBIA **ERO** **FS ID**  
**WIRA #**  
**Waterway** **Type**  
**Latitude** **Longitude**  
**Topo Quad 1:24:000** SHELTON VALLEY  
**Direction/Landmark (mile post, cross roads, township/range)**

### What happened

**Spills Program Oil Spill?** N

**Incident Date** 3/25/2013 **Received Date** 3/26/2013 9:45  
**Medium** SOIL  
**Material** SEWAGE/SLUDGE  
**Quantity** **Unit**  
**Source** WASTEWATER TREATMENT PLANT  
**Cause** EQUIPMENT FAILURE  
**Activity** ROUTINE/NORMAL OPERATIONS  
**Impact** POTENTIAL POLLUTION/RELEASE  
**Vessel Name**  
**Hull Number**

### Primary Potentially Responsible Party Information

**First Name** **Last Name**  
**Name**  
**Business Name** DAYTON WWTP  
**Street Address** 800 STOCKTON ROAD  
**Other Address**  
**City** DAYTON (COLUMBIA **State** WA **Zip**  
**Phone** (509) 382-2937 **Ext** **Type** Business  
**E-mail** WWTPDAYTON@HOTMAIL.COM

### Additional Contact Information

**Name** **Phone** **Ext** **Type**

### More Information

WA0020729 Dayton..

\*Receiving Water  
 (if applicable):None of the spill went in any surface water. Stopped at least 75 yards from the River.  
 Duration of Overflow:10-15 min.  
 Volume of Overflow:800-1200 gallons  
 Other Comments:Ended in depression 30FT x10ft x .25 ft on City property only.  
 Notifications  
 Columbia County Environmental Health Dept Joseph Siumara  
 ph: 509 520-5907fax: 509-397-6239, email: jfiumara@co.walla-walla.wa.usDate:3/26/2013  
 WWTP Permit (Patrick McGuire)  
 ph: 509-3293567 fax: 509-329-3470, email: pmcg461@ecy.wa.govDate:3/25/2013  
 DOE (Mike Hepp)  
 ph: 509-329-3536, fax: 509-329-3570, email: mhhep461@ecy.wa.govDate:3/26/2013

NOTE: Mike Hepp will log this event into the ERTS system and notify the City of the assigned ERTS number.

Response (include additional pages if necessary)  
 Cleanup Method:  
 Vacuumed with vac trailer emptied into drying bed along with wash. Area covered with 6in of dirty sand mix. Liquid spill waste returned to headworks.

Steps to prevent

## Department of Ecology - Environmental Report Tracking System

**ERTS # 640183**

reoccurrence:

Will visually check crossover pipe for plug before pumping thickened sludge from thickener to primary digester.

Entry Person Alexander, Kim

Entry Date 3/26/2013

## Department of Ecology - Environmental Report Tracking System

**ERTS # 640183**

### Referral

<b>Referral Method</b>		<b>Person Referred to</b> HEPP, MIKE	<b>Referral #</b> 166885
<input type="radio"/> E-mail ERTS number		<b>Phone</b> (509) 329-3536 <b>Fax</b> (509) 329-3529	<b>Primary</b> <input type="checkbox"/>
<input checked="" type="radio"/> E-mail attachment		<b>E-mail</b> MHEP461@ECY.WA.GOV	
<input type="radio"/> Print		<b>Program/Organization</b> WATER QUALITY	
<input type="radio"/> Telephone		<b>Address</b> 4601 N. MONROE STREET	
		<b>City</b> SPOKANE <b>WA</b> 99205-1295	
		<b>Region/Location</b> ERO	
		<b>Referral Date</b> 3/26/2013	

### Followup (None)