

United Parcel Service (UPS) Spokane Site

Toxics Cleanup Program

Ecology Proposes to Remove Site from Hazardous Sites List

The United Parcel Service-Spokane site is located at 1016 North Bradley Road in Spokane Valley, Spokane County, Washington (see Map on page 2). Contractors removed approximately 95 yards of petroleum-contaminated soil from the site. This work was completed under Ecology's Voluntary Cleanup Program. As a result of this completed work, Ecology plans to remove the site from the Hazardous Sites List.

Hazardous Sites List

The Hazardous Sites List is a record of contaminated sites throughout the state that are ranked on a scale of one to five. One represents the greatest potential threat to human health and the environment; five represents the least potential threat. The United Parcel Service-Spokane site ranked a three because of the petroleum contaminated soil at the site.

A site may be removed from the Hazardous Sites List after cleanup work is completed and it meets Ecology's criteria. Ecology proposes to remove this site based upon the following information:

- Review of the cleanup reports.
- Supporting documentation.
- State standards for cleanup of petroleum product in soil have been sufficiently achieved at the site.

No further action is needed at the site.

Ecology Invites Your Comments

- Review: You are invited to review the associated site documents and comment on the proposed delisting.
- Send: You may send your comments to Patti Carter at Ecology from July 11, 2011 through August 9, 2011 for consideration. The box on the right provides details about where to review documents and send comments.

Investigations and Cleanup

In October 1987 a spill occurred at the UPS-Spokane site while an Underground Storage Tank (UST) was being filled for a test. Gasoline leaked onto the ground, and it was removed and replaced with clean fill material. The area where the spill occurred was then covered with concrete.

Fact Sheet July 2011

July 2011

Comments Accepted July 11, 2011 through August 9, 2011

Para asistencia en Español Richelle Perez 360/407-7528

Если вам нужно помощь по русский, звоните

Tatyana Bistrevesky 509/928-7617

Technical Questions

Patti Carter WA Department of Ecology 4601 N. Monroe St. Spokane WA 99205-1295 509/329-3522 patti.carter@ecy.wa.gov

Public Involvement Questions

Carol Bergin WA Department of Ecology 4601 N. Monroe St. Spokane, WA 99205-1295 509/329-3546 carol.bergin@ecy.wa.gov

Document Review Locations WA Department of Ecology

Kari Johnson Public Disclosure WA Department of Ecology 4601 N. Monroe St. Spokane, WA 99205-1295 Call for appointment or CDs of the documents 509/329-3415

Ecology's Website:

https://fortress.wa/gov/ecy/gsp/Sitepage. aspx?/csid=1272

Facility Site ID No. 672 Cleanup Site ID No. 1272

United Parcel Service (UPS) Spokane Site


In 1990, five separate USTs were removed. During the removal process at each location, petroleum contaminated soil was found. The contaminated soil was removed and replaced with clean fill material. Including the soil removed in 1987, a total of 95 cubic yards of soil was removed from the site.

Soil sampling was conducted in each area to determine if any contaminants were remaining. Lead was found in the soil but it did not exceed state standards. No petroleum products were detected.

The site remains an active UPS facility and new USTs remain at the locations where tanks were removed.

What Happens Next?

After the 30-day comment period, Ecology will review and respond to the public comments received about the removal of the site from the Hazardous Sites List. If no significant changes are made, the site will be removed from the Hazardous Sites List. The removal will be reflected in the August 2011 edition of the Site Register which is a special edition entitled "Hazardous Sites List."



If you need this publication in an alternative format, call Carol Bergin at 509/329-3546. Persons with hearing loss, call 711 for Washington Relay Service. Persons with speech disability call 877-833-6341

