

J H Kelly Inc Cleanup Site

Proposed removal from the Hazardous Sites List

CONTACT & INFORMATION

Comments accepted April 11–May 12, 2019

Submit comments online http://cs.ecology.commenti

nput.com/?id=x2SEr

by mail

Aaren Fiedler Cleanup Project Manager WA Department of Ecology PO Box 47775 Olympia, WA 98504-7775

Document review locations Longview Public Library 1600 Louisiana Street Longview, WA 98632 360-442-5300

WA Department of Ecology Southwest Regional Office 300 Desmond Drive SE Lacey, WA 98503 By appointment, call 360-407-6365

Site webpage

https://fortress.wa.gov/ ecy/gsp/Sitepage.aspx? csid=10377

Site identification numbers Facility Site ID: 74552527 Cleanup Site ID: 10377

Why you received this information

The J H Kelly Inc. cleanup site (site) is located at 821 3rd Ave in Longview. You may live or own property near the site, which is the reason you received this information in the mail.

Public comment invited

The Department of Ecology (Ecology) ranked the site's relative risk and put it on the state's Hazardous Sites List. After cleanup, Ecology determined the site meets state cleanup levels and no further cleanup actions are needed. Once a ranked site is cleaned up, a public comment period is required before a site can be removed from the list.

Ecology invites your comments about removing the site from the list from **April 11 to May 12, 2019**.

After the comment period, we will post responses to the site webpage (see blue box on the left). Your comments are considered before the site is removed from the Hazardous Sites List.

Cleanup

In 1991 petroleum hydrocarbon contamination was found at the site when two underground storage tanks were removed. Additional soil was excavated from the area where the tanks were located and the soil and wastewater were removed from the property. Groundwater was monitored at the site off and on from 1991 to 2016.

Ecology ranked the site a 2, with 1 being the highest relative level of concern compared to other sites. After ranking the site, it was placed it on the Hazardous Sites List.

In 2016, the owner entered Ecology's Voluntary Cleanup Program to clean up the site on their own. Soil collected from where the former underground tanks were located verified that petroleum contamination of soil was below state cleanup levels.

The owner installed groundwater monitoring wells near the former tank locations. Quarterly groundwater sampling conducted in 2018 confirmed that petroleum contamination of groundwater at the site was below state cleanup levels.

The site webpage has links to relevant documents.



Toxics Cleanup Program PO Box 47775 Olympia, WA 98504-7775

Public comment period for removing the J H Kelly Inc. Site from the Hazardous Sites List



Public Comments Accepted April 11–May 12, 2019

Facility Site ID: 74552527

Site Location 821 3rd Ave, Longview, WA

¿Habla Español?

Si necesita esta información en español contáctenos a <u>preguntas@ecy.wa.gov</u>.

Accommodation & Alternative Format

To request ADA accommodation for disabilities, or printed materials in a format for the visually impaired, call Ecology at 360-407-6831 or visit https://ecology.wa.gov/accessibility.

People with impaired hearing may call Washington Relay Service at 711. People with speech disability may call TTY at 877-833-6341.