

Cleanup Site Details

Cleanup Site ID: 11198

Cleanup Site ID: 11198 **Facility/Site ID:** 95362668 **UST ID:** 3262 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Texaco-Bulk Plant [Glossary](#)
Alternate Names: D & D DISTRIBUTORS, Texaco-Bulk Plant

LOCATION

Address: 606 Wagon Rd **City:** DAYTON **Zip Code:** 99328 **County:** Columbia
Latitude: 46.31519 **Longitude:** -117.99172 **WRIA:** 32 **Legislative District:** 16 **Congressional District:** 5 **TRS:** 10N 38E 25

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 6/27/2017 **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No
Site Manager: Eastern Region **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TEXACO BULK PLANT	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	B	B				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		7/17/1992
LUST - Report Received	Completed		7/17/1992
Petroleum Impacts to Groundwater Model Remedies	Completed		6/27/2017
Site Status Changed to NFA	Completed		6/27/2017