

Cleanup Site Details

Cleanup Site ID: 11462

Cleanup Site ID: 11462 Facility/Site ID: 29985737 UST ID: 2645 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Busch Distributors Inc UST 2645 [Glossary](#)

Alternate Names: BUSCH DISTRIBUTORS INC UST 2645, STATELINE BULK PLANT/CARDLOCK

LOCATION

Address: 7603 SR 270 City: PULLMAN Zip Code: 99163 County: Whitman
Latitude: 46.73300 Longitude: -117.05006 WRIA: 34 Legislative District: 9 Congressional District: 5 TRS: 14N 46E 5

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 10/23/2015 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Busch Distributors, Inc. LUST	Upland	No Further Action Required	EA	Eastern Region	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/12/2010
Initial Investigation / Federal Preliminary Assessment	Completed		1/14/2011
Early Notice Letter(s)	Completed		1/14/2011
LUST - Report Received	Completed		1/26/2011
LUST - Notification	Completed		1/26/2011
LUST - Report Received	Completed		3/21/2011
LUST - Report Received	Completed		6/21/2011
LUST - Report Received	Completed		10/3/2011
LUST - Report Received	Completed		1/17/2012
LUST - Report Received	Completed		5/4/2012

Cleanup Site Details

Cleanup Site ID: 11462

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		1/18/2013
LUST - Report Received	Completed		2/15/2013
LUST - Report Received	Completed		6/12/2013
VCP Opinion on Site Cleanup Plan	Completed	7/17/2013	10/14/2013
VCP Opinion on Site Cleanup	Completed	9/23/2015	10/23/2015
Petroleum Impacts to Groundwater Model Remedies	Completed		10/9/2015
Site Status Changed to NFA	Completed		10/23/2015