

# Cleanup Site Details

Cleanup Site ID: 11796

Cleanup Site ID: 11796      Facility/Site ID: 29      UST ID: 11040      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Reynolds Metals Aluminum Smelter

[Glossary](#)

**Alternate Names:** CHINOOK VENTURES INC LONGVIEW, LONGVIEW ALUMINUM LLC, Millennium Bulk Logistics Longview, Millennium Bulk Terminals Longview, Millennium Bulk Terminals Longview LLC, Reynolds Metals Aluminum Smelter, REYNOLDS METALS CO, REYNOLDS METALS CO LONGVIEW, REYNOLDS METALS CO LONGVIEW REDUCTION PL, REYNOLDS METALS PCB

## LOCATION

**Address:** 4029 INDUSTRIAL WAY      **City:** LONGVIEW      **Zip Code:** 98632      **County:** Cowlitz  
**Latitude:** 46.14243      **Longitude:** -123.00141      **WRIA:** 25      **Legislative District:** 19      **Congressional District:** 3      **TRS:** 8N 3W 38

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA (RCRA Corrective Action)      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 5 - Lowest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Penfield, Sarah      **Responsible Unit:** Industrial Section      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
LONGVIEW ALUMINUM LLC	Upland	No Further Action Required	SWP	Skyllingstad, Paul	Ecology-supervised or conducted
Drum Soil Cleanup	Upland	No Further Action Required	SWP	Skyllingstad, Paul	Independent Action
UST Longview Aluminum LLC	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	SW	Barrett, Guy (IN)	Independent Action
Reynolds Metals Aluminum Smelter Sitewide Cleanup	Upland	Cleanup Started	SWP	Yamazaki, Shingo	Ecology-supervised or conducted
Columbia River Sediment	Sediment	No Further Action Required	SWP	Barrett, Guy	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	C				
Conventional Contaminants, Organic	C					
Metals - Other	C	C				
Petroleum Products-Unspecified	C					
Petroleum-Diesel	RB					
Petroleum-Other	C	C				
Polychlorinated biPhenyls (PCB)	R		R			
Polycyclic Aromatic Hydrocarbons	C	B		RB		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 11796

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/2/1989
Independent Report Review - Unpaid	Completed	1/2/1989	10/24/1989
Initial Investigation / Federal Preliminary Assessment	Completed		4/29/1989
Site Hazard Assessment/Federal Site Inspection	Completed	9/1/1990	12/1/1990
Hazardous Sites Listing/NPL	Completed		2/5/1991
LUST - Site Assessment Report	Completed		9/20/2004
LUST - Notification	Completed		11/5/2004
Remedial Investigation and/or Feasibility Study	Completed	6/1/2006	6/1/2009
Remedial Investigation and/or Feasibility Study	Completed	3/1/2007	4/1/2009
Order/Decree/Amendment	Canceled		6/15/2007
Order/Decree/Amendment	In Process	2/16/2012	
Remedial Investigation and/or Feasibility Study	Completed	2/17/2012	2/12/2015
Interim Action - Plan	Completed	1/2/2014	6/2/2014
Order/Decree/Amendment	In Process	6/2/2014	
Cleanup Action Plan	Completed	1/18/2016	12/14/2018
Interim Action - Construction	Completed	10/26/2016	11/18/2016
Order/Decree/Amendment	In Process	11/19/2018	
Cleanup Action - Engineering Design	In Process	12/14/2018	