

Cleanup Site Details

Cleanup Site ID: 11797

Cleanup Site ID: 11797 Facility/Site ID: 95415874 UST ID: 2954 Site Page Site Documents View Map

Cleanup Site Name: Columbia Gorge Aluminum

Alternate Names: COLUMBIA ALUMINUM, COLUMBIA ALUMINUM UST 2954, Columbia Gorge Aluminum, COLUMBIA GORGE ALUMINUM

COMPANY, GOLDENDALE ALUMINUM COMPANY

LOCATION

Address: 85 JOHN DAY DAM RD City: GOLDENDALE Zip Code: 98620 County: Klickitat

Latitude: 45.72959 Longitude: -120.70085 WRIA: 31 Legislative District: 14 Congressional District: 3 TRS: 3N 17E 20

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA (RCRA Corrective Action) NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Johnson, Dave Responsible Unit: Industrial Section Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Site-wide cleanup	Upland	Cleanup Started	I	Schrieve, Garin	Ecology-supervised or conducted
Proposed Goldendale Energy Project portion of the site (redevelopment)	Upland	Cleanup Started	ı	Yamazaki, Shingo	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Restrict Land Use	12/4/1987	Vol. 244, pp.34- 47	Klickitat	1-31; 36

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	С	С				
Petroleum-Diesel	С					
Petroleum-Other	С					
Polycyclic Aromatic Hydrocarbons	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	11/10/1988	5/25/1989
Hazardous Sites Listing/NPL	Completed		8/30/1990
Order/Decree/Amendment	In Process	3/26/2014	
Remedial Investigation and/or FS Work Plan	Completed	5/1/2014	8/24/2015
Remedial Investigation and/or Feasibility Study	In Process	8/24/2015	

Toxics Cleanup Program Report Generated: 4/25/2024 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Remedial Investigation and/or FS Work Plan	Completed	6/26/2019	9/23/2020			
Order/Decree/Amendment	In Process	11/24/2021				
Remedial Investigation and/or Feasibility Study	In Process	11/24/2021				
Cleanup Action Plan	In Process	11/24/2021				

Cleanup Site ID: 11797