

Cleanup Site ID: 12095

## Cleanup Site Details

Facility/Site ID: 450 UST ID: 7829 Site Page Site Documents View Map

Cleanup Site ID: 12095

Cleanup Site Name: Boise Cascade Mill Glossary

Alternate Names: BOISE CASCADE COMPLEX YAKIMA, BOISE CASCADE CORP, Boise Cascade Corp Yakima, Boise Cascade Mill, BOISE CASCADE PLYWOOD LOG YARD, Boise Cascade Yakima, BOISE CASCADE YAKIMA COMPLEX, Boise Cascade Yakima LUST, DUNOLLIE

ENTERPRISES LLC YAKIMA, Old Yakima Landfill, Yakima Landfill, YAKIMA RESOURCES, YAKIMA RESOURCES LLC

LOCATION

Address: 805 N 7TH ST City: YAKIMA Zip Code: 98901 County: Yakima

Latitude: 46.61472 Longitude: -120.49905 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 13N 19E 18

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? Yes

Site Manager: Zinza, John Responsible Unit: Central Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boise Cascade Mill	Upland	Cleanup Started	CE	Zinza, John	Ecology-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	С	С	С				
Benzene	С						
Halogenated Solvents		С					
Lead	С		С				
Metals - Other	С	С	С				
Other Non-Halogenated Organics	С		С				
Petroleum-Diesel	С	С	С				
Petroleum-Gasoline	С						
Petroleum-Other	С						
Polychlorinated biPhenyls (PCB)	S						
Polycyclic Aromatic Hydrocarbons	С						

Key:

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected R - Remediated

RB - Remediated-Below

Toxics Cleanup Program Report Generated: 4/26/2024 Page 1 of 2



## Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Discovery/Release Report Received	Completed		12/1/2008			
Non-LUST Ind Report Received	Completed		6/26/2014			
Early Notice Letter(s)	Completed		3/4/2016			
Order/Decree/Amendment	In Process	6/3/2016				
Remedial Investigation and/or FS Work Plan	Completed	2/17/2017	1/29/2019			
Remedial Investigation and/or Feasibility Study	In Process	1/29/2019				
Interim Action - Plan	Canceled		5/4/2023			
Remedial Investigation and/or Feasibility Study	Planned	8/1/2023	12/31/2023			

Cleanup Site ID: 12095