DEPARTMENT OF
ECOLOGY
 State of Washington

## Cleanup Site Details

Cleanup Site ID: 12299

Cleanup Site ID: 1	2299 <b>Fac</b>	ility/Site ID:	21489	UST ID: N/A		Site Pag	e <u>Site Doc</u>	<u>uments</u>	View Map
Cleanup Site Name	: Independent M	etals Storage	Lot						<u>Glossary</u>
Alternate Names:	Independent Meta	ls Storage Lo	t						
LOCATION									
Address: 703 S M	ONROE ST			City: SEATTL	.E	Zip Code: 98	108 <b>Cou</b>	nty: King	
Latitude: 47.53105	Longitude:	-122.32519	<b>WRIA:</b> 9	Legislative D	strict:	11 Congressi	onal District:	9 <b>TR</b>	<b>S:</b> 24N 4E 32
DETAIL									
Status: No Furth	er Action	NFA	Received?	Yes		ls F	'SI site?	No	
Statute: MTCA		NFA	Date:	6/18/2020		Cu	rrent VCP?	No Pa	st VCP? Yes
Site Rank: 4 - Low-	Moderate Risk	NFA	Reason:	Voluntary Clear	nup Prog	ram Review Bro	wnfield?	No	
Site Manager: Coo	k, Jason	Resp	onsible Unit:	Northwest		Act	ive Institutio	nal Contre	ol? No
CLEANUP UNITS									
Cleanup U	nit Name	Unit Type	Unit	Status	Resp Unit	Unit Manager		Current Process	
Independent Metals	Storage Lot	Upland	No Further A	ction Required	NW	Cook, Jason	Stand	lard Volur	tary Cleanup
ACTIVE INSTITUTIO		S							
Instrument Type	Restriction Media	Rest	rictions/Requi	rements	D	ate Recor		ording ounty	Tax Parcel
There are no current	Institutional Cont	rols in effect f	or this site.						
AFFECTED MEDIA	& CONTAMINAN	TS							
Contaminant		-				MED	•		
Arsenic			So	il Ground	water	MED Surface Water		Air	Bedrock
			So B	il Ground		MED Surface Water B	A Sediment	Air	Bedrock
Lead						Surface Water		Air	Bedrock
Lead Mercury			В	RE		Surface Water B		Air	Bedrock
			B	B		Surface Water B		Air	Bedrock
Mercury	Drganics		B	RE B B		B B B		Air	Bedrock
Mercury Metals - Other	-		B	RE B B		Surface Water B B B B		Air	Bedrock
Mercury Metals - Other Other Halogenated 0	-		B B B B	B B B B		Surface Water B B B B		Air	Bedrock
Mercury Metals - Other Other Halogenated ( Other Non-Halogena	-		B B B B B B B	B B B B		Surface Water B B B B		Air	Bedrock
Mercury Metals - Other Other Halogenated ( Other Non-Halogena Petroleum-Diesel	-		B B B B B B B B B	B B B B		Surface Water B B B B		Air	Bedrock
Mercury Metals - Other Other Halogenated ( Other Non-Halogena Petroleum-Diesel Petroleum-Gasoline	ated Organics		B B B B B B B B B	B B B B		Surface Water B B B B		Air	Bedrock
Mercury Metals - Other Other Halogenated ( Other Non-Halogena Petroleum-Diesel Petroleum-Gasoline Petroleum-Other	ated Organics		B B B B B B B B B B	RE RE B B B B C C C C C C C C C C C C C		Surface Water B B B B B C C C C C C C C C C C C C C		Air	Bedrock Bedrock
Mercury Metals - Other Other Halogenated ( Other Non-Halogena Petroleum-Diesel Petroleum-Gasoline Petroleum-Other Polychlorinated biPh	enyls (PCB)		B B B B B B B B B B B B B	RE B B B B B B B B B		Surface Water B B B B B C C C C C C C C C C C C C C		Air	Bedrock



## **Cleanup Site Details**

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/1/2012
Initial Investigation / Federal Preliminary Assessment	Completed		2/14/2014
Early Notice Letter(s)	Completed		2/24/2014
Site Hazard Assessment/Federal Site Inspection	Completed	12/15/2014	10/27/2015
Hazardous Sites Listing/NPL	Completed		10/30/2015
VCP Receipt of Plan or Report	Completed		2/6/2019
VCP Receipt of Plan or Report	Completed		2/6/2019
VCP Opinion on Site Cleanup	Completed	2/20/2019	6/18/2020
VCP Opinion on Site Cleanup	Completed		10/23/2019
VCP Receipt of Plan or Report	Completed		1/21/2020
VCP Receipt of Plan or Report	Completed		3/31/2020
VCP Receipt of Plan or Report	Completed		5/6/2020
Site Status Changed to NFA	Completed		6/18/2020
Remove site from Hazardous Sites List	Completed		8/25/2020