

Cleanup Site Details

Cleanup Site ID: 12972

Cleanup Site ID: 12972 Facility/Site ID: 19373 UST ID: 620116 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: COULTER CREEK HATCHERY [Glossary](#)

Alternate Names: COULTER CREEK HATCHERY

LOCATION

Address: E 41 COULTER CREEK RD City: BELFAIR Zip Code: 98528 County: Mason
Latitude: 47.40750 Longitude: -122.81800 WRIA: 15 Legislative District: 35 Congressional District: 6 TRS: 22N 1W 9

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? Yes
Statute: MTCA NFA Date: 6/20/2017 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Johnston, Carol Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Emergency generator LUST	Upland	No Further Action Required	SW	Johnston, Carol	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel		RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Site Assessment Report	Completed		7/22/2014
LUST - Notification	Completed		7/22/2014
Early Notice Letter(s)	Completed		1/21/2016
VCP Receipt of Plan or Report	Completed		2/8/2017
VCP Opinion on Site Cleanup	Completed	2/13/2017	6/20/2017
Petroleum Impacts to Groundwater Model Remedies	Completed		3/22/2017
Site Status Changed to NFA	Completed		6/20/2017