

Cleanup Site Details

Cleanup Site ID: 13162

Cleanup Site ID: 13162 Facility/Site ID: 18558 UST ID: 620294 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Bargren Building aka Peterson Brothers Garage [Glossary](#)

Alternate Names: Bargren Building aka Peterson Brothers Garage, Tenth & K Professional Bldg, Tenth & K Professional Bldg aka Peterson Brothers Garage

LOCATION

Address: 1002 MARTIN LUTHER KING JR WAY City: TACOMA Zip Code: 98405 County: Pierce
Latitude: 47.25274 Longitude: -122.45232 WRIA: 10 Legislative District: 27 Congressional District: 6 TRS:

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 6/13/2017 Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: Independent Cleanup Reviewed by Ecology Brownfield? No
Site Manager: Johnston, Carol Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bargren Building LUST	Upland	No Further Action Required	SW	Johnston, Carol	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		5/9/2016
LUST - Site Characterization Report	Completed		5/11/2016
Early Notice Letter(s)	Completed		11/30/2016
Petroleum Contaminated Soil Model Remedies	Completed		6/13/2017
Site Status Changed to NFA	Completed		6/13/2017