DEPARTMENT OF ECOLOGY
State of Washington

Cleanup Site Details

Cleanup Site ID: 13258

Cleanup Site ID: 13258 **Facility/Site ID:** 3178 **UST ID:** 620323 Site Page | Site Documents | View Map

Cleanup Site Name: Morris Waste Oil UST Glossary

Alternate Names: Marybeth & Michael Morris, Morris Waste Oil UST

LOCATION

Address: 816 NE 57TH ST **City:** SEATTLE **Zip Code:** 98105 **County:** King

Latitude: 47.67025 **Longitude:** -122.31927 **WRIA:** 8 **Legislative District:** 43 **Congressional District:** 7 **TRS:** 25N 4E 8

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No

Statute: MTCA **NFA Date:** 5/15/2017 **Current VCP?** No **Past VCP?** No

Site Rank: N/A **NFA Reason:** Initial Investigation **Brownfield?** No

Site Manager: Northwest Region **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Morris Waste Oil UST	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Benzene	RB					
Non-Halogenated Solvents	RB					
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB					
Petroleum-Other	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		6/22/2016
Petroleum Contaminated Soil Model Remedies	Completed		12/14/2016
Non-LUST Ind Report Received	Completed		12/14/2016
Initial Investigation / Federal Preliminary Assessment	Completed		5/4/2017
Site Status Changed to NFA	Completed		5/15/2017