

# Cleanup Site Details

Cleanup Site ID: 13289

Cleanup Site ID: 13289      Facility/Site ID: 15218      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Lakeside 24 Hour Fuel

[Glossary](#)

Alternate Names: Lakeside 24 Hour Fuel

## LOCATION

Address: 16835 LEWIS RIVER RD      City: COUGAR      Zip Code: 98616      County: Cowlitz  
Latitude: 46.05122      Longitude: -122.30175      WRIA: 27      Legislative District: 20      Congressional District: 3      TRS: 7N 4E 34

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 8/2/2017      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Fiedler, Aaren      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

| Cleanup Unit Name     | Unit Type | Unit Status                | Resp Unit | Unit Manager   | Current Process            |
|-----------------------|-----------|----------------------------|-----------|----------------|----------------------------|
| Lakeside 24 Hour Fuel | Upland    | No Further Action Required | SW        | Fiedler, Aaren | Standard Voluntary Cleanup |

## ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

| MEDIA                          |      |             |               |          |     |         |
|--------------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant                    | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Benzene                        | RB   |             |               |          |     |         |
| Lead                           | RB   |             |               |          |     |         |
| Other Non-Halogenated Organics | RB   |             |               |          |     |         |
| Petroleum-Diesel               | RB   |             |               |          |     |         |
| Petroleum-Gasoline             | B    |             |               |          |     |         |
| Petroleum-Other                | RB   |             |               |          |     |         |

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

| Activity                                   | Status    | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received     | Completed |            | 6/19/2017                 |
| VCP Receipt of Plan or Report              | Completed |            | 6/19/2017                 |
| VCP Opinion on Site Cleanup                | Completed | 6/19/2017  | 8/2/2017                  |
| VCP Receipt of Plan or Report              | Completed |            | 7/11/2017                 |
| Petroleum Contaminated Soil Model Remedies | Completed |            | 8/2/2017                  |

# Cleanup Site Details

Cleanup Site ID: 13289

| SITE ACTIVITIES            |           |            |                              |
|----------------------------|-----------|------------|------------------------------|
| Activity                   | Status    | Start Date | End Date/<br>Completion Date |
| Site Status Changed to NFA | Completed |            | 8/2/2017                     |