

## Cleanup Site Details

Cleanup Site ID: 13290

Facility/Site ID: 35259244 Cleanup Site ID: 13290 **UST ID: 8604** Site Page **Site Documents** View Map

Cleanup Site Name: 7-Eleven 22561 (2016) **Glossary** 

Alternate Names: 7 ELEVEN STORE 22561, 7-Eleven #22561, 7-Eleven 22561, 7-Eleven 22561 (2016), 7-Eleven 22561A, SOUTHLAND CORP

22561

LOCATION

City: SEATTLE Address: 3280 SW Avalon Way **Zip Code: 98126** County: King

Latitude: 47.56438 Longitude: -122.37583 Legislative District: 34 Congressional District: 7 TRS: 24N 3E 13

**DETAIL** 

NFA Received? Yes Is PSI site? Status: No Further Action Nο

NFA Date: **Current VCP?** Past VCP? No Statute: MTCA 6/19/2017 No

Site Rank: N/A NFA Reason: Initial Investigation **Brownfield?** No

Site Manager: Northwest Region Responsible Unit: Northwest **Active Institutional Control?** No

**CLEANUP UNITS** 

| Cleanup Unit Name     | Unit Type | Unit Status                | Resp<br>Unit | Unit Manager     | Current Process    |
|-----------------------|-----------|----------------------------|--------------|------------------|--------------------|
| 7-Eleven 22561 (2016) | Upland    | No Further Action Required | NW           | Northwest Region | Independent Action |

## **ACTIVE INSTITUTIONAL CONTROLS**

| Instrument Type | Restriction<br>Media | Restrictions/Requirements | Date | Recording<br>Number | Recording County | Tax Parcel |
|-----------------|----------------------|---------------------------|------|---------------------|------------------|------------|
|-----------------|----------------------|---------------------------|------|---------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

|                                | MEDIA |             |               |          |     |         |  |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|--|
| Contaminant                    | Soil  | Groundwater | Surface Water | Sediment | Air | Bedrock |  |
| Benzene                        | RB    |             |               |          |     |         |  |
| Other Non-Halogenated Organics | RB    |             |               |          |     |         |  |
| Petroleum-Gasoline             | RB    |             |               |          |     |         |  |

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected

RA - Remediated-Above R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

| Activity   | Status    | Start Date | End Date/<br>Completion Date |
|--|-----------|------------|------------------------------|
| Site Discovery/Release Report Received                 | Completed |            | 11/3/2016                    |
| LUST - Notification                                    | Completed |            | 11/3/2016                    |
| LUST - Site Assessment Report                          | Completed |            | 1/5/2017                     |
| LUST - Report Received                                 | Completed |            | 6/5/2017                     |
| Petroleum Contaminated Soil Model Remedies             | Completed |            | 6/5/2017                     |
| Initial Investigation / Federal Preliminary Assessment | Completed |            | 6/19/2017                    |
| Site Status Changed to NFA                             | Completed |            | 6/19/2017                    |

**Toxics Cleanup Program** Report Generated: 4/26/2024 Page 1 of 1