

Cleanup Site ID: 1385

Cleanup Site Details

Facility/Site ID: 2202 UST ID: 9901 Site Page Site Documents View Map

Cleanup Site ID: 1385

Cleanup Site Name: Port of Seattle Terminal 117

Alternate Names: MALARKEY ASPHALT CO, MALARKEY ASPHALT COMPANY, Port of Seattle Terminal 117, SEATTLE PORT DALLAS AVE,

Seattle Port Terminal 117

LOCATION

Address: 8700 DALLAS AVE S City: SEATTLE Zip Code: 98108 County: King

Latitude: 47.52651 Longitude: -122.31150 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 24N 4E 33

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: Federal - CERCLA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: N/A Brownfield? No

Site Manager: EPA Responsible Unit: EPA Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Seattle Port Terminal 117	Upland	Cleanup Started	EPA	EPA	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Sediment	Restrict Land Use, Prohibit Soil Disturbance	11/16/2017	20171113000218	King	332404-1111

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the Environmental Covenants Registry List.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Asbestos					S			
Base/Neutral/Acid Organics	С	С	С					
Dioxins/Furans	С							
Halogenated Organics					S			
Metals Priority Pollutants	С	С	С					
Non-Halogenated Solvents					S			
Pesticides-Unspecified	С	С						
Petroleum-Diesel	В							
Petroleum-Other		С						
Polychlorinated biPhenyls (PCB)	С	С	С					
Polycyclic Aromatic Hydrocarbons	С	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above

S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 4/25/2024 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Hazardous Sites Listing/NPL	Completed		8/27/1991			
Site Hazard Assessment/Federal Site Inspection	Completed		8/27/1991			
LUST - Report Received	Completed		4/27/1992			
LUST - Notification	Completed		5/7/1992			
LUST - Report Received	Completed		1/31/2000			
Interim Action	Canceled	4/29/2003	8/8/2008			

Cleanup Site ID: 1385