

Cleanup Site Details

Cleanup Site ID: 15156

Cleanup Site ID: 15156 Facility/Site ID: 66765272 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Georgia-Pacific Consumer Products

[Glossary](#)

Alternate Names: FORT JAMES CAMAS LLC, FORT JAMES CAMAS MILL, FORT JAMES LLC MILL, G-P CONSUMER PRODUCTS CAMAS LLC, G-P CONSUMER PRODUCTS CARMAS LLC, Georgia Pacific Consumer Operations, GEORGIA PACIFIC CONSUMER PRODUCTS, Georgia Pacific Consumer Products (Camas, GEORGIA PACIFIC CONSUMER PRODUCTS (Camas) LLC, Georgia Pacific Consumer Products Camas LLC, Georgia-Pacific Consumer Products, JAMES RIVER II, JAMES RIVER PAPER CO CAMAS

LOCATION

Address: 401 NE ADAMS ST **City:** CAMAS **Zip Code:** 98607 **County:** Clark
Latitude: 45.58484 **Longitude:** -122.40565 **WRIA:** 28 **Legislative District:** 18 **Congressional District:** 3 **TRS:** 1N 3E 47

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Lyon, Mady **Responsible Unit:** Industrial Section **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Mill site	Upland	Awaiting Cleanup	I	Lyon, Mady	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Asbestos	S					
Benzene	S					
Corrosive Wastes	S					
Dioxins/Furans	S					
Lead	S					
Metals - Other	S					
Non-Halogenated Solvents	S					
Petroleum-Other	S					
Polychlorinated biPhenyls (PCB)	S					
Polycyclic Aromatic Hydrocarbons	S					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 15156

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/24/2020
Order/Decree/Amendment	In Process	8/28/2020	
Remedial Investigation and/or FS Work Plan	In Process	1/3/2022	