

# Cleanup Site Details

Cleanup Site ID: 2096

Cleanup Site ID: 2096      Facility/Site ID: 2776343      UST ID: 508050      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Superlon Plastics Co Inc      [Glossary](#)

Alternate Names: SUPERION PLASTICS CO INC, Superlon Plastics, SUPERLON PLASTICS CO INC

## LOCATION

Address: 2116 TAYLOR WAY      City: TACOMA      Zip Code: 98421      County: Pierce  
Latitude: 47.27030      Longitude: -122.38408      WRIA: 10      Legislative District: 27      Congressional District: 9      TRS: 21N 3E 35

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 1 - Highest Assessed Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Meng, Sam      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SUPERLON PLASTICS CO INC	Upland	Cleanup Started	SW	Mercuri, Joyce	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C	C			
Base/Neutral/Acid Organics	S	S				
Halogenated Organics		C				
Lead	C	C	C			
Metals - Other	S	S				
Metals Priority Pollutants	S	S	C			
Non-Halogenated Solvents	S	S				
Other Halogenated Organics	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Other	C	C				
Phenolic Compounds	S	S				
Polycyclic Aromatic Hydrocarbons	S	S				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 2096

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		7/28/1990
Site Discovery/Release Report Received	Completed		2/26/1991
Initial Investigation / Federal Preliminary Assessment	Completed		7/6/2007
Early Notice Letter(s)	Completed		7/6/2007
Site Hazard Assessment/Federal Site Inspection	Completed	3/17/2009	1/20/2010
Interim Action - Plan	Completed	11/10/2009	12/10/2009
Interim Action - Construction	Completed	12/10/2009	1/26/2012
Hazardous Sites Listing/NPL	Completed		1/20/2010
Interim Action - Plan	Completed	2/5/2011	5/3/2012
Remedial Investigation and/or FS Work Plan	Completed	3/1/2011	5/12/2011
Remedial Investigation and/or FS Work Plan	Completed	7/13/2011	9/19/2011
Interim Action - Plan	Completed	9/23/2011	9/30/2011
Interim Action - Construction	Completed	9/23/2011	4/3/2012
Interim Action - Construction	Completed	9/30/2011	4/5/2012
Remedial Investigation and/or FS Work Plan	Completed	10/1/2011	12/5/2011
Interim Action - Plan	Completed	1/1/2012	4/3/2012
Remedial Investigation and/or FS Work Plan	Completed	1/15/2012	4/5/2012
Remedial Investigation and/or Feasibility Study	Completed	4/5/2012	10/1/2013
Remedial Investigation and/or Feasibility Study	Completed	9/1/2014	12/17/2014
Order/Decree/Amendment	In Process	9/30/2015	
Remedial Investigation and/or Feasibility Study	In Process	3/7/2022	