State of Washington		Cleanup						Cleanup	Site ID: 2146	
Cleanup Site ID: 2146 Faci	lity/Site ID:	1884322	UST ID: N/A			Site Page	e <u>Site</u>	Documents	<u>View Map</u>	
Cleanup Site Name: Weyerhaeuser I	Mill A								<u>Glossary</u>	
Alternate Names: SOUTH TERMINA	L PIER 1 HE	WITT TERM, We	yerhaeuser Mill	A, WE	YERHAE	USER MIL		RMER		
LOCATION										
Address: 3500 TERMINAL AVE			City: EVERETT			Zip Code: 98201 County: Snohom				
Latitude: 47.97515 Longitude: -	122.22536	WRIA: 7	Legislative Di	strict:	38 C	ongressio	onal Dist	rict: 2 TI	RS: 29N 5E 30	
DETAIL										
Status: Awaiting Cleanup	NFA	Received?	No		Is PSI site?			Yes		
Statute: MTCA	Ite: MTCA NFA Date:					Cur	urrent VCP? No Past VCP? No			
Site Rank: N/A	Reason:	N/A Bro					wnfield? No			
Site Manager: Hardwick, Ryan	Resp	onsible Unit:	Headquarters			Act	ive Instit	utional Cont	rol? No	
CLEANUP UNITS										
Cleanup Unit Name	Unit Type	Unit St	atus	Resp Unit	Unit	Unit Manager		Current Process		
WEYERHAEUSER MILL A FORMER	Sediment	Awaiting C	Cleanup	HQ	Adolp	Adolphson, Pete		No Process		
WEYERHAEUSER MILL A FORMER	Upland	Awaiting C	Cleanup	HQ	Hard	Hardwick, Ryan		Ecology-supervised or conducted		
ACTIVE INSTITUTIONAL CONTROLS	5									
Instrument Type Restriction Media	Rest	rictions/Require	Requirements E		Date	Record Numl		Recording County	Tax Parcel	
There are no current Institutional Contr	rols in effect f	or this site.								
There are no current Institutional Contr		or this site.					'			
There are no current Institutional Contr AFFECTED MEDIA & CONTAMINAN		or this site.				MEDI	A			
		or this site. Soil	Ground	water	Surface	MEDI. e Water	A	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN			Ground	water	Surfac			ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic				water	Surface			ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures				water	Surfac		Sedime	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN				water	Surfac		Sedime C	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other			С	water	Surfac		Sedime C C	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants			С	water	Surfac		Sedime C C C	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents			С	water	Surfac		Sedime C C C C	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins			С	water	Surfac		Sedime C C C C S	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins Other Deleterious Substances			С	water	Surfac		Sedime C C C C S S	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins Other Deleterious Substances Other Halogenated Organics		Soil	C	water	Surfac		Sedime C C C C S S	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins Other Deleterious Substances Other Halogenated Organics Petroleum Products-Unspecified		Soil	C	water	Surfac		Sedime C C C C S S S C	ent Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins Other Deleterious Substances Other Halogenated Organics Petroleum Products-Unspecified Petroleum-Gasoline		Soil Soil C	C C C C C C	water	Surfac		Sedime C C C C S S S C	ent Air ent I	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans		Soil Soil C	C C C C C C	water	Surfac		Sedime C C C S S C S S	ent Air ent I Air	Bedrock	
AFFECTED MEDIA & CONTAMINAN Contaminant Arsenic Bioassay Benthic Failures Dioxins/Furans Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Organotins Other Deleterious Substances Other Halogenated Organics Petroleum Products-Unspecified Petroleum-Gasoline Phenolic Compounds		Soil Soil C	C C C C C	water	Surfac		Sedime C C C S S C S S C	ent Air ent I	Bedrock	



Cleanup Site Details

Key: B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Site Discovery/Release Report Received	Completed		12/31/2003				
Site Hazard Assessment/Federal Site Inspection	Canceled	4/9/2007	8/19/2009				
Initial Investigation / Federal Preliminary Assessment	Completed		6/4/2010				
Early Notice Letter(s)	Completed		6/21/2011				
Order/Decree/Amendment	In Process	2/3/2012					
Remedial Investigation and/or FS Work Plan	Completed	8/10/2012	11/21/2014				
Remedial Investigation and/or Feasibility Study	In Process	11/21/2014					
Interim Action - Plan	Completed	5/18/2015	9/11/2015				
Order/Decree/Amendment	In Process	9/25/2015					
Interim Action - Construction	Completed	8/15/2016	2/14/2017				
Interim Action - Performance Monitoring	Planned	2/14/2022	12/31/2023				
Cleanup Action Plan	Planned	1/1/2023					
Cleanup Action - Engineering Design	Planned	9/30/2024					
Cleanup - Construction	Planned	9/30/2024					