

Cleanup Site Details

Cleanup Site ID: 2581

Cleanup Site ID: 2581 Facil	ity/Site ID: 443	8651	UST ID: N/A		Site Pag	je s	Site Docu	iments	View Map	
Cleanup Site Name: Bay Wood Produ	ucts								<u>Glossary</u>	
Alternate Names: BAY WOOD PROD	OUCTS									
LOCATION										
Address: 200 W MARINE VIEW DR			City: EVERE	ГТ	Zip Code: 98	201	Coun	ty: Snc	bhomish	
Latitude: 48.01686 Longitude: -1	122.20963 WI	RIA: 7	Legislative Di	strict: 3	8 Congress	ional	District:	2 TR	S: 29N 5E 7	
DETAIL										
Status: Cleanup Started	NFA Re	ceived?	No		ls	PSI si	te? `	Yes		
Statute: MTCA	NFA Da	te:	N/A		Cu	rrent	VCP?	No Pa	ast VCP? No	
Site Rank: 4 - Low-Moderate Risk	NFA Re	ason:	N/A		Bre	ownfi	eld?	No		
Site Manager: Hargrove, Amy	Respon	sible Unit:	Headquarters		Active Institutional Control? No					
CLEANUP UNITS										
Cleanup Unit Name	Unit Type	Unit	Status	Resp Unit	Unit Manage	r	C	Current	Process	
BAY WOOD PRODUCTS	Sediment	Cleanu	p Started	HQ	Morman, Josh	۱	Ecology-	sed or conducted		
BAY WOOD PRODUCTS	Upland	Cleanu	p Started	HQ	Hargrove, Am	Hargrove, Amy		Ecology-supervised or conducted		
ACTIVE INSTITUTIONAL CONTROLS										
Instrument Type Restriction Media	Restric	tions/Requi	rements	Da	te Recor			rding unty	Tax Parcel	
There are no current Institutional Contro	ols in effect for t	his site.								
AFFECTED MEDIA & CONTAMINANT	ſS									
					MED	IA				
Contaminant		So	il Ground	water	Surface Water		liment	Air	Bedrock	
Bioassay Benthic Failures							C			
Dioxins/Furans							С			
Metals Priority Pollutants							S			
Non-Halogenated Solvents							S			
Other Deleterious Substances		S	S				С			
Petroleum Products-Unspecified		S	S			S				
Phenolic Compounds							S			
Polychlorinated biPhenyls (PCB)		S	S				S			
Polycyclic Aromatic Hydrocarbons							S			
	nfirmed Above C nediated	Cleanup Leve	el RA - Rem RB - Rem							
SITE ACTIVITIES										
Activity				5	Status Start Date			End Date/ Completion Date		
Order/Decree/Amendment				In	Process					
Toxics Cleanup Program Report Generated: 4/26/2024 Pa						ge 1 of 2				



Г

Cleanup Site Details

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action	Completed	6/1/1986	12/31/1986
Site Characterization	Completed	1/1/1989	6/30/1989
Interim Action	Completed	9/1/1995	10/31/1995
Site Hazard Assessment/Federal Site Inspection	Completed	9/15/2008	12/29/2008
Hazardous Sites Listing/NPL	Completed		1/30/2009
Remedial Investigation and/or Feasibility Study	In Process	6/9/2009	
Interim Action - Plan	Completed	4/18/2014	10/10/2014
Cleanup Action Plan	In Process	6/30/2015	
Interim Action - Construction	Completed	12/1/2020	4/30/2021