

# Cleanup Site Details

Cleanup Site ID: 3033

<b>Cleanup Site ID:</b> 3033	<b>Facility/Site ID:</b> 101	<b>UST ID:</b> N/A	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>	
<b>Cleanup Site Name:</b> Silver Mountain Mine						
<b>Alternate Names:</b> Silver Mountain Mine						
<b>LOCATION</b>						
<b>Address:</b> COUNTY RD 4371		<b>City:</b> LOOMIS	<b>Zip Code:</b> 98827	<b>County:</b> Okanogan		
<b>Latitude:</b> 48.74487	<b>Longitude:</b> -119.55812	<b>WRIA:</b> 49	<b>Legislative District:</b> 7	<b>Congressional District:</b> 4	<b>TRS:</b> 38N 26E 34	
<b>DETAIL</b>						
<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No				
<b>Statute:</b> Federal - CERCLA	<b>NFA Date:</b> 12/6/2021	<b>Current VCP?</b> No		<b>Past VCP?</b> No		
<b>Site Rank:</b> 0 - NPL Site (Fed HRS Score)	<b>NFA Reason:</b> Ecology Supervised/Conducted Cleanup	<b>Brownfield?</b> No				
<b>Site Manager:</b> Central Region	<b>Responsible Unit:</b> Central	<b>Active Institutional Control?</b> Yes				
<b>CLEANUP UNITS</b>						
<b>Cleanup Unit Name</b>	<b>Unit Type</b>	<b>Unit Status</b>	<b>Resp Unit</b>	<b>Unit Manager</b>	<b>Current Process</b>	
Silver Mountain Mine	Upland	No Further Action Required	CE	Central Region	Federal-supervised or conducted	
<b>ACTIVE INSTITUTIONAL CONTROLS</b>						
<b>Instrument Type</b>	<b>Restriction Media</b>	<b>Restrictions/Requirements</b>	<b>Date</b>	<b>Recording Number</b>	<b>Recording County</b>	<b>Tax Parcel</b>
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict Domestic Ground Water Extraction/Well Installation, Prevent the Reuse or Relocation of Site Soil	12/4/1996	847844	Okanogan	9826340005
Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the <a href="#">Environmental Covenants Registry List</a> .						
<b>AFFECTED MEDIA &amp; CONTAMINANTS</b>						
<b>MEDIA</b>						
<b>Contaminant</b>	<b>Soil</b>	<b>Groundwater</b>	<b>Surface Water</b>	<b>Sediment</b>	<b>Air</b>	<b>Bedrock</b>
Arsenic	RA	RA				
Metals Priority Pollutants	RA	RA				
<b>Key:</b> B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above S - Suspected                      R - Remediated                      RB - Remediated-Below						
<b>SITE ACTIVITIES</b>						
<b>Activity</b>	<b>Status</b>		<b>Start Date</b>	<b>End Date/ Completion Date</b>		
Remedial Investigation and/or Feasibility Study	Completed		10/1/1988	1/19/1990		
Cleanup Action Plan	Completed		1/17/1990	3/27/1990		
Cleanup Action - Engineering Design	Completed		6/1/1990	9/1/1990		
Cleanup - Construction	Completed		9/9/1991	8/31/1993		
Hazardous Sites Listing/NPL	Completed			2/22/1995		
O & M	In Process		7/10/1997			
Periodic Review	Completed		4/1/2002	9/16/2002		
<b>Toxics Cleanup Program</b>						

# Cleanup Site Details

Cleanup Site ID: 3033

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Periodic Review	Completed	6/1/2007	2/29/2008
Periodic Review	Completed	5/23/2012	9/20/2012
Periodic Review	Completed	4/20/2017	9/1/2017
Remove site from Hazardous Sites List	Completed		12/6/2021
Site Status Changed to NFA	Completed		12/6/2021
Periodic Review	In Process	9/25/2022	