

Cleanup Site Details

Cleanup Site ID: 304

Cleanup Site ID: 304 Facility/Site ID: 2662 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: March Point Landfill [Glossary](#)

Alternate Names: MARCH POINT LANDFILL, TEXACO PS OFFSITE DUMP, WHITMARSH DUMP TEXACO PS OFFS, WHITMARSH LANDFILL

LOCATION

Address: 807 S March Point Rd City: ANACORTES Zip Code: 98221 County: Skagit

Latitude: 48.46363 Longitude: -122.53088 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS:

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: WPCA - Ch. 90.48 RCW NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Horne, David Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
MARCH POINT LANDFILL	Sediment	No Further Action Required	HQ	Adolphson, Pete	Ecology-supervised or conducted
MARCH POINT LANDFILL	Upland	Cleanup Started	HQ	Horne, David	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	S	S	S	B		
Conventional Contaminants, Organic	S	S	S	B		
Dioxins/Furans				B		
Metals Priority Pollutants	S	S	S	B		
Non-Halogenated Solvents	S	S	S	B		
Pesticides-Unspecified	S	S	S	B		
Petroleum Products-Unspecified	S	S	S	B		
Phenolic Compounds	S	S	S	B		
Polychlorinated biPhenyls (PCB)	S	C	S	B		
Polycyclic Aromatic Hydrocarbons	S	S	S	B		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 304

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment/Federal Site Inspection	Completed	7/4/2002	1/24/2003
Hazardous Sites Listing/NPL	Completed		1/24/2003
Early Notice Letter(s)	Completed		11/30/2007
Remedial Investigation and/or Feasibility Study	Completed	5/6/2008	2/7/2017
Order/Decree/Amendment	Completed	3/4/2009	2/8/2021
Cleanup Action Plan	Completed	6/14/2017	2/16/2020
Cleanup Action - Engineering Design	In Process	2/16/2020	
Order/Decree/Amendment	In Process	2/11/2021	
Cleanup - Construction	Planned	5/1/2025	8/31/2025