

Cleanup Site ID: 3418

Cleanup Site Details

Facility/Site ID: 2864 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3418

Cleanup Site Name: Central Waterfront

Alternate Names: CENTRAL WATERFRONT, Old City Dump, ROEDER AVE LANDFILL

LOCATION

Address: F ST City: BELLINGHAM Zip Code: 98225 County: Whatcom

Latitude: 48.75545 Longitude: -122.48999 WRIA: 1 Legislative District: 42 Congressional District: 2 TRS: 38N 2E 25

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Rapp, John Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Roeder Ave Landfill	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Chevron Bellingham Terminal 100- 1350	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Olivine Corp Hilton Ave Uplands	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted
Colony Wharf (BCI)	Upland	Cleanup Started	NW	Rapp, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic		С						
Base/Neutral/Acid Organics	S	S	S					
Benzene	С	С						
Conventional Contaminants, Organic	С							
Halogenated Organics	S	S	S					
Lead	С	С						
Mercury		С						
Metals - Other		С						
Metals Priority Pollutants	С	С						
Non-Halogenated Solvents	С	С	С		S			
Other Halogenated Organics					S			
Other Non-Halogenated Organics		С						

Toxics Cleanup Program Report Generated: 4/26/2024 Page 1 of 2



Cleanup Site Details

State of Washington	Cle	Cleanup Site Details				Cleanup Site ID: 3418		
Contaminant		Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Petroleum Products-Unspecified		S	S	S				
Petroleum-Diesel		С	С					
Petroleum-Gasoline		С	С					
Petroleum-Other		С	С	С		S		
Phenolic Compounds		S	S	S		S		
Polycyclic Aromatic Hydrocarbons		С				S		

B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level

RA - Remediated-Above RB - Remediated-Below

R - Remediated

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Order/Decree/Amendment	In Process			
Site Hazard Assessment/Federal Site Inspection	Completed	3/21/1995	6/29/1995	
Hazardous Sites Listing/NPL	Completed		8/22/1995	
VCP Opinion on Remedial Investigation Work Plan	Canceled	4/21/1998		
VCP Opinion on Remedial Investigation Work Plan	Completed	6/26/1998	10/15/1999	
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	4/30/2009	
Remedial Investigation and/or Feasibility Study	Completed	5/1/2002	3/30/2018	
Interim Action - Plan	Completed	7/31/2012	9/30/2012	
Interim Action - Construction	Completed	9/30/2012	5/31/2016	
Cleanup Action Plan	In Process	11/13/2018		