

Cleanup Site ID: 3632

Cleanup Site Details

Facility/Site ID: 500 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3632

Cleanup Site Name: Yakima Railroad Glossary

Alternate Names: Yakima Railroad

LOCATION

Address: 1ST ST CORRIDOR City: YAKIMA Zip Code: 98901 County: Yakima

Latitude: 46.61097 Longitude: -120.51088 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 13N 18E 13

DETAIL

Status: Construction Complete- NFA Received? No Is PSI site? No

Performance Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Parker, Kyle Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Yakima Railroad
 Upland
 Construction Complete-Performance Monitoring
 CE
 Parker, Kyle
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	С	С			S	

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	Completed		
Order/Decree/Amendment	Completed		
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	Completed	2/11/1992	
Order/Decree/Amendment	Completed	8/28/1992	
Order/Decree/Amendment	Completed	1/28/1993	
Remedial Investigation and/or Feasibility Study	Completed	6/1/1995	7/29/1999
Order/Decree/Amendment	In Process	7/19/1995	

Toxics Cleanup Program Report Generated: 4/26/2024 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	In Process	7/29/1999	

Cleanup Site ID: 3632