Cleanup Site Details

Cleanup Site ID: 3862

Cleanup Site ID: 3862 **Facility/Site ID:** 2696 **UST ID:** N/A Site Page | Site Documents | View Map

Cleanup Site Name: Everett Landfill Tire Fire Glossary

Alternate Names: EVERETT CITY OF LANDFILL, EVERETT LANDFILL TIRE FIRE

LOCATION

Address: 2900 36TH ST **City:** EVERETT **Zip Code:** 98201 **County:** Snohomish

Latitude: 47.97000 **Longitude:** -122.19237 **WRIA:** 7 **Legislative District:** 38 **Congressional District:** 2 **TRS:** 29N 5E 29

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No

Site Manager: Becker, Sunny **Responsible Unit:** Northwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Everett Landfill Tire Fire	Upland	Cleanup Started	NW	Becker, Sunny	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Amended Environmental Covenant	Groundwater, Soil	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Ongoing Maintenance of Remedy, Prohibit Removal or Alteration of Existing Buildings	5/14/2008	200805140922	Snohomish	29053200101200

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Base/Neutral/Acid Organics	C	C	C		C	
Conventional Contaminants, Inorganic	S	S	S		S	
Conventional Contaminants, Organic	C	C	C		S	
Metals - Other	S	S	S			
Metals Priority Pollutants	C	C	C		C	
Pesticides-Unspecified	S	S	S			
Petroleum Products-Unspecified	C	C	C		S	
Phenolic Compounds	S	S	S			
Polychlorinated biPhenyls (PCB)	C	S	S		C	
Polycyclic Aromatic Hydrocarbons	C	C	C		S	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 3862

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	7/1/1990	12/31/1993
Site Discovery/Release Report Received	Completed		12/31/1993
Interim Action	Completed	6/13/1994	11/1/1995
Remedial Investigation and/or Feasibility Study	Completed	6/13/1994	5/1/1996
Hazardous Sites Listing/NPL	Completed		11/1/1995
Cleanup Action Plan	Completed	11/1/1996	2/28/2001
Interim Action	Completed	8/1/1997	6/30/1998
O & M	Completed	6/30/1998	1/1/2003
Order/Decree/Amendment	In Process	3/1/2000	
O & M	In Process	1/1/2003	