

Cleanup Site ID: 3956

Cleanup Site Details

Facility/Site ID: 11293827 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 3956

Cleanup Site Name: Schwerin Concaves Walla Walla Glossary

Alternate Names: SCHWERIN CONCAVES, Schwerin Concaves Walla Walla

LOCATION

Address: 1106 SAPPOLIL RD City: WALLA WALLA Zip Code: 99362 County: Walla Walla

Latitude: 46.12191 Longitude: -118.23660 WRIA: 32 Legislative District: 16 Congressional District: 5 TRS: 7N 37E 6

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Treccani, Sandra Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Schwerin Concaves Walla Walla
 Upland
 Cleanup Started
 EA
 Treccani, Sandra
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	С	С	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		4/27/1989
Site Discovery/Release Report Received	Completed		10/15/1990
Early Notice Letter(s)	Completed		5/12/1999
Remedial Investigation and/or Feasibility Study	Completed	3/1/2000	6/30/2009
Site Hazard Assessment/Federal Site Inspection	Completed	6/14/2000	8/18/2000
Hazardous Sites Listing/NPL	Completed		8/29/2000
Interim Action	Completed	11/1/2002	3/31/2003

Toxics Cleanup Program Report Generated: 4/25/2024 Page 1 of 1