

Cleanup Site Details

Cleanup Site ID: 4146

Cleanup Site ID: 4146	Facility/Site ID: 21945598	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Duwamish Marine Center					Glossary	
Alternate Names: Duwamish Marine Center						
LOCATION						
Address: 6365 1ST AVE S		City: SEATTLE	Zip Code: 98108	County: King		
Latitude: 47.54504	Longitude: -122.33581	WRIA: 9	Legislative District: 11	Congressional District: 7	TRS: 24N 4E 30	
DETAIL						
Status: Cleanup Started	NFA Received? No	Is PSI site? No				
Statute: MTCA	NFA Date: N/A	Current VCP? No		Past VCP? Yes		
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No				
Site Manager: Nale, Cliff	Responsible Unit: Northwest	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Duwamish Marine Center	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C					
Metals - Other	C					
Metals Priority Pollutants	C					
Non-Halogenated Solvents	S	C				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	C					
Polycyclic Aromatic Hydrocarbons	C	S				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed			1/26/2001		
Initial Investigation / Federal Preliminary Assessment	Completed			4/6/2001		
VCP Opinion on Cleanup Action	Canceled		5/7/2002			
VCP Opinion on Site Cleanup	Completed		4/1/2005	6/1/2005		
Toxics Cleanup Program		Report Generated: 4/23/2024			Page 1 of 2	

Cleanup Site Details

Cleanup Site ID: 4146

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Status Request	Completed	3/31/2006	6/16/2006
VCP Receipt of Plan or Report	Completed		4/28/2006
VCP Opinion on Cleanup Action	Completed	6/5/2006	7/3/2006
VCP Opinion on Cleanup Action Plan	Completed	9/20/2007	2/13/2008
VCP Opinion on Cleanup Action Plan	Completed	3/20/2008	4/7/2008
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/2010	2/8/2012
Remedial Investigation and/or FS Work Plan	Completed	9/2/2011	1/15/2014
Order/Decree/Amendment	In Process	9/2/2011	
Hazardous Sites Listing/NPL	Completed		2/15/2012
Remedial Investigation and/or Feasibility Study	Completed	1/15/2014	9/30/2020
Remedial Investigation and/or Feasibility Study	In Process	10/1/2020	