Cleanup Site Details

Cleanup Site ID: 4203

Cleanup Site ID: 4203 **Facility/Site ID:** 32584416 **UST ID:** 97219 Site Page | Site Documents | View Map

Cleanup Site Name: Airport Kwik Stop Glossary

Alternate Names: AIRPORT KWIK STOP, CRANDALLS AIRPORT GROCERY

LOCATION

Address: HWY 31 & GREENHOUSE RD **City:** IONE **Zip Code:** 99139 **County:** Pend Oreille

Latitude: 48.71440 **Longitude:** -117.41430 **WRIA:** 62 **Legislative District:** 7 **Congressional District:** 5 **TRS:** 37N 43E 7

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No

Site Manager: Kercher, Beth **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Airport Kwik Stop	Upland	Cleanup Started	EA	Kercher, Beth	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Benzene	C	C				
Methyl tertiary-butyl ether	S					
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/11/2008
Site Discovery/Release Report Received	Completed		5/13/2008
Initial Investigation / Federal Preliminary Assessment	Completed		5/28/2008
Early Notice Letter(s)	Completed		6/17/2008
Site Characterization	Completed	4/26/2010	8/31/2011
LUST - Site Characterization Report	Completed		10/15/2010
LUST - Site Characterization Report	Completed		1/5/2011
LUST - Report Received	Completed		5/9/2011

Cleanup Site Details

Cleanup Site ID: 4203

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		5/31/2011
LUST - Report Received	Completed		7/6/2011
LUST - Report Received	Completed		9/1/2011
Remedial Investigation and/or FS Work Plan	Completed	11/14/2011	4/1/2012
LUST - Report Received	Completed		11/28/2011
Remedial Investigation and/or Feasibility Study	Completed	12/30/2011	6/28/2013
LUST - Report Received	Completed		4/16/2012
LUST - Report Received	Completed		5/25/2012
LUST - Report Received	Completed		6/15/2012
LUST - Report Received	Completed		6/22/2012
Interim Action - Plan	Completed	7/30/2012	9/29/2012
Interim Action - Construction	Completed	10/1/2012	12/21/2012
Notice of Intent to Incur Remedial Action Costs	Completed		11/20/2012
Interim Action - Construction	Completed	11/30/2012	4/1/2012
Interim Action - Performance Monitoring	Completed	12/21/2012	3/31/2014
LUST - Report Received	Completed		2/1/2013
LUST - Report Received	Completed		5/7/2013
LUST - Report Received	Completed		7/2/2013
LUST - Report Received	Completed		7/8/2013
LUST - Report Received	Completed		10/11/2013
LUST - Report Received	Completed		11/25/2013
LUST - Report Received	Completed		2/19/2014
Interim Action - Plan	Completed	6/4/2014	7/3/2014
Interim Action - Construction	Completed	9/15/2014	10/24/2014
Interim Action - Plan	Completed	12/6/2016	5/10/2017
Interim Action - Construction	Completed	4/24/2017	7/14/2017