

Cleanup Site Details

Cleanup Site ID: 4257

Cleanup Site ID: 4257 Facility/Site ID: 12832256 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Smith Kem Ellensburg Inc

[Glossary](#)

Alternate Names: SMITH KEM ELLENSBURG INC

LOCATION

Address: 200 S RAILROAD AVE City: ELLENSBURG Zip Code: 98926 County: Kittitas
Latitude: 46.99113 Longitude: -120.55463 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 17N 18E 2

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Mefford, John	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Smith Kem Ellensburg Inc	Upland	Cleanup Started	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic		C				
Halogenated Pesticides	C	C				
Metals Priority Pollutants	S	S				
Non-Halogenated Pesticides	B	B				
Petroleum-Diesel	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/17/2008
Early Notice Letter(s)	Completed		6/2/2008
Site Hazard Assessment/Federal Site Inspection	Completed	6/30/2008	8/14/2008
Hazardous Sites Listing/NPL	Completed		8/14/2008
Non-LUST Ind Report Received	Completed		8/9/2013
Non-LUST Ind Report Received	Completed		10/8/2014

Cleanup Site Details

Cleanup Site ID: 4257

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		10/23/2014
Non-LUST Ind Report Received	Completed		3/9/2015
Non-LUST Ind Report Received	Completed		7/10/2015
Order/Decree/Amendment	Completed	9/25/2015	4/7/2023
Remedial Investigation and/or FS Work Plan	Completed	2/29/2016	8/1/2016
Non-LUST Ind Report Received	Completed		6/1/2016
Remedial Investigation and/or Feasibility Study	Completed	8/1/2016	1/21/2022
Order/Decree/Amendment	In Process	4/12/2022	
Cleanup Action Plan	Completed	5/26/2022	5/3/2023
Cleanup Action - Engineering Design	In Process	5/3/2023	