

# Cleanup Site Details

Cleanup Site ID: 4520

Cleanup Site ID: 4520      Facility/Site ID: 8122259      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Scott Paper Mill      [Glossary](#)

Alternate Names: CITY OF ANACORTES, DAKOTA CREEK INDUSTRIES, MJB PROPERTIES, INC., Scott Paper Mill, Scott Paper Mill Former

## LOCATION

Address: 17TH-20TH ST & R AVE      City: ANACORTES      Zip Code: 98221      County: Skagit  
Latitude: 48.50748      Longitude: -122.61028      WRIA: 3      Legislative District: 40      Congressional District: 2      TRS: 35N 2E 19

## DETAIL

Status: Construction Complete-Performance Monitoring      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Park, Hun Seak      Responsible Unit: Headquarters      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Scott Paper Mill Former	Sediment	Construction Complete-Performance Monitoring	HQ	Park, Hun Seak	Ecology-supervised or conducted
Scott Paper Mill Former	Upland	Construction Complete-Performance Monitoring	HQ	Park, Hun Seak	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use, Prohibit Soil Disturbance	11/20/2013	201311200045	Skagit	P32963; P32965

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic					C	
Conventional Contaminants, Organic				C	S	
Dioxin/Dibenzofuran Compounds	C			C		
Metals Priority Pollutants	C	C	C	C	S	
Other Deleterious Substances				C		
Petroleum Products-Unspecified	C	S	S	C	S	
Polychlorinated biPhenyls (PCB)	C	S	S	C	S	
Polycyclic Aromatic Hydrocarbons	C		C	C		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 4520

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		10/24/2003
Site Hazard Assessment/Federal Site Inspection	Completed	11/3/2003	12/5/2004
Hazardous Sites Listing/NPL	Completed		12/5/2004
Remedial Investigation and/or Feasibility Study	Completed	9/6/2006	11/28/2008
Cleanup Action Plan	Completed	12/1/2008	5/29/2009
Cleanup - Construction	Completed	12/1/2011	9/24/2012
Cleanup Action - Engineering Design	Completed	12/1/2011	5/1/2012