

Cleanup Site Details

Cleanup Site ID: 4550

Cleanup Site ID: 4550 Facility/Site ID: 2251399 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Monte Cristo Mining Area [Glossary](#)

Alternate Names: MONTE CRISTO MINING AREA

LOCATION

Address: 4 MI SE BARLOW PASS MTN LOOP HWY City: SILVERTON Zip Code: 98241 County: Snohomish
Latitude: 47.99167 Longitude: -121.37500 WRIA: 4 Legislative District: 39 Congressional District: 1 TRS: 29N 11E 22

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Rice, Justin Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|--------------------------|-----------|-----------------|-----------|--------------|---------------------------------|
| Monte Cristo Mining Area | Sediment | Cleanup Started | CE | Rice, Justin | Ecology-supervised or conducted |
| Monte Cristo Mining Area | Upland | Cleanup Started | CE | Rice, Justin | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|----------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Metals - Other | C | S | C | C | S | |
| Metals Priority Pollutants | C | S | C | C | S | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| Site Discovery/Release Report Received | Completed | | 6/23/2003 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 7/8/2003 |
| Early Notice Letter(s) | Completed | | 9/8/2003 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 10/7/2003 | 1/15/2004 |
| Hazardous Sites Listing/NPL | Completed | | 1/31/2004 |
| Remedial Investigation and/or Feasibility Study | Completed | 8/24/2011 | 12/29/2017 |
| Interim Action - Plan | Completed | 1/1/2015 | 6/17/2015 |