

Cleanup Site Details

Cleanup Site ID: 4765

Cleanup Site ID: 4765 Facility/Site ID: 2050 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: North Boeing Field Georgetown Steam Plant [Glossary](#)

Alternate Names: BOEING NORTH FIELD, GEORGETOWN STEAMPLANT, North Boeing Field Georgetown Steam Plant, North Boeing Field Georgetown Steamplant, SEATTLE CITY LIGHT STEAMPLANT GEORGETOWN

LOCATION

Address: 7370 E MARGINAL WAY S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.54093 **Longitude:** -122.31338 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 29

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Schwarz, Julia **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
North Boeing Field Georgetown Steamplant	Upland	Cleanup Started	NW	Schwarz, Julia	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene					C	
Conventional Contaminants, Inorganic	C	C	S			
Corrosive Wastes	C	B	S			
Dioxins/Furans	S	C	S			
Halogenated Organics	C	C	S			
Halogenated Solvents					C	
Metals - Other	S	S	S			
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum Products-Unspecified	C	C	S			
Petroleum-Diesel					C	
Petroleum-Gasoline					C	
Petroleum-Other					C	
Polychlorinated biPhenyls (PCB)	S	C	S		S	

Cleanup Site Details

Cleanup Site ID: 4765

Key:

B - Below Cleanup Level

C - Confirmed Above Cleanup Level

RA - Remediated-Above

S - Suspected

R - Remediated

RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/1993	8/25/1993
Hazardous Sites Listing/NPL	Completed		8/25/1993
Site Discovery/Release Report Received	Completed		5/27/1999
Initial Investigation / Federal Preliminary Assessment	Completed		5/28/1999
Early Notice Letter(s)	Completed		9/7/1999
Site Hazard Assessment/Federal Site Inspection	Completed	9/11/2001	2/6/2001
Order/Decree/Amendment	In Process	1/1/2006	
Interim Action	Completed	5/1/2006	5/31/2006
Remedial Investigation and/or Feasibility Study	In Process	9/20/2008	