

Cleanup Site Details

Cleanup Site ID: 4846

Cleanup Site ID: 4846	Facility/Site ID: 4781157	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: Shell Oil Tank Farm					Glossary	
Alternate Names: Shell Bulk Plant, Shell Oil Tank Farm, Shell Oil Tank Farm Former						
LOCATION						
Address: 14TH ST & Q AVE		City: ANACORTES	Zip Code: 98221	County: Skagit		
Latitude: 48.51128	Longitude: -122.61165	WRIA: 3	Legislative District: 40	Congressional District: 2	TRS: 35N 2E 19	
DETAIL						
Status: Cleanup Complete-Active O&M/Monitoring	NFA Received? No	Is PSI site? Yes				
Statute: MTCA	NFA Date: N/A	Current VCP? No	Past VCP? No			
Site Rank: 3 - Moderate Risk	NFA Reason: N/A	Brownfield? No				
Site Manager: Maurer, Christopher	Responsible Unit: Headquarters	Active Institutional Control? Yes				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Shell Oil Tank Farm Former	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	HQ	Maurer, Christopher	Ecology-supervised or conducted	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict Access, Ongoing Maintenance of Remedy, Maintain/Protect Monitoring System	5/16/2017	201705160070	Skagit	P32956
Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the Environmental Covenants Registry List .						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents	C	B				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	S					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Order/Decree/Amendment	In Process					
Site Discovery/Release Report Received	Completed			1/12/2006		
Initial Investigation / Federal Preliminary Assessment	Completed			2/17/2006		
Early Notice Letter(s)	Completed			2/21/2006		
Toxics Cleanup Program						

Cleanup Site Details

Cleanup Site ID: 4846

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	2/28/2008	7/11/2008
Remedial Investigation and/or Feasibility Study	Completed	6/2/2008	2/3/2014
Hazardous Sites Listing/NPL	Completed		7/11/2008
Cleanup Action Plan	Completed	2/3/2013	2/3/2014
Cleanup Action - Engineering Design	Completed	2/3/2014	7/29/2014
Cleanup - Construction	Completed	9/4/2014	6/26/2015
O & M	Completed	7/14/2015	7/14/2020
Periodic Review	Completed	5/16/2017	9/20/2020
Monitoring	In Process	7/14/2020	
Periodic Review	In Process	9/20/2020	