

Cleanup Site Details

Cleanup Site ID: 4901

Cleanup Site ID: 4901 Facility/Site ID: 386 UST ID: 10589 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Big B Mini Mart [Glossary](#)

Alternate Names: Big B LLC, BIG B MINI MART, Flying B 29

LOCATION

Address: 1611 CANYON RD City: ELLENSBURG Zip Code: 98926 County: Kittitas
Latitude: 46.97711 Longitude: -120.54344 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 17N 18E 11

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Exxon Big B Mini Mart	Upland	Cleanup Started	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		10/30/1990
Site Discovery/Release Report Received	Completed		11/1/1990
Site Hazard Assessment/Federal Site Inspection	Completed	4/15/1991	7/15/1991
Early Notice Letter(s)	Completed		6/19/1991
Early Notice Letter(s)	Completed		6/21/1991
Hazardous Sites Listing/NPL	Completed		8/27/1991
LUST - Report Received	Completed		9/27/1991
Early Notice Letter(s)	Completed		4/7/2011
Order/Decree/Amendment	Completed	3/24/2014	12/10/2018

Cleanup Site Details

Cleanup Site ID: 4901

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or FS Work Plan	Completed	4/22/2015	10/2/2017
Interim Action - Plan	Completed	9/1/2016	10/20/2016
Interim Action - Construction	Completed	10/20/2016	11/28/2017
Remedial Investigation and/or Feasibility Study	Completed	10/2/2017	12/10/2018
Order/Decree/Amendment	Canceled	5/18/2018	10/22/2018
Order/Decree/Amendment	In Process	10/22/2018	
Interim Action - Plan	Completed	5/20/2019	6/21/2019
Interim Action - Construction	Completed	6/21/2019	7/19/2019
Interim Action - Performance Monitoring	Completed	9/4/2019	11/7/2019
Order/Decree/Amendment	In Process	1/31/2020	
Cleanup Action Plan	Completed	10/12/2020	11/23/2020
Cleanup - Construction	Completed	6/13/2021	6/30/2022
LUST - Report Received	Completed		1/29/2024