# Cleanup Site Details

**Cleanup Site ID: 5089**

**Cleanup Site ID:** 5089 **Facility/Site ID:** 2322 **UST ID:** 5754 Site Page | Site Documents | View Map

**Cleanup Site Name:** Circle K 1461 Glossary

**Alternate Names:** CIRCLE K 01461, CIRCLE K 1461, CIRCLE K Sta 1461

## LOCATION

**Address:** 2350 24TH AVE E **City:** SEATTLE **Zip Code:** 98112 **County:** King

**Latitude:** 47.64008 **Longitude:** -122.30182 **WRIA:** 8 **Legislative District:** 43 **Congressional District:** 7 **TRS:** 25N 4E 21

## DETAIL

**Status:** Cleanup Started **NFA Received?** No **Is PSI site?** No

**Statute:** MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

**Site Rank:** 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No

**Site Manager:** Myers, Dale R **Responsible Unit:** Northwest **Active Institutional Control?** No

## CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|---|---|---|---|---|---|
| Circle K 1461 | Upland | Cleanup Started | NW | Myers, Dale R | Ecology-supervised or conducted |

## ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|---|---|---|---|---|---|---|
| There are no current Institutional Controls in effect for this site. | | | | | | |

## AFFECTED MEDIA & CONTAMINANTS

| | MEDIA | | | | | |
|---|---|---|---|---|---|---|
| **Contaminant** | **Soil** | **Groundwater** | **Surface Water** | **Sediment** | **Air** | **Bedrock** |
| Benzene | C | C | | | | |
| Non-Halogenated Solvents | C | C | | | | |
| Petroleum-Gasoline | C | C | | | | |

**Key:**
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|---|---|---|---|
| Site Discovery/Release Report Received | Completed | | 8/7/1989 |
| LUST - Notification | Completed | | 8/7/1989 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 10/12/1989 |
| LUST - Report Received | Completed | | 3/6/1990 |
| LUST - Report Received | Completed | | 8/23/1990 |
| LUST - Report Received | Completed | | 11/9/1990 |
| Early Notice Letter(s) | Completed | | 3/20/1991 |
| Cleanup Action Plan | Completed | 4/15/1991 | 7/1/1992 |

DEPARTMENT OF ECOLOGY
State of Washington

# Cleanup Site Details

**Cleanup Site ID: 5089**

**SITE ACTIVITIES**

| Activity | Status | Start Date | End Date/ Completion Date |
|---|---|---|---|
| Order/Decree/Amendment | In Process | 2/19/1992 | |
| LUST - Report Received | Completed | | 6/1/1992 |
| Remedial Investigation and/or Feasibility Study | Completed | 6/1/1992 | 7/1/1992 |
| O & M | Canceled | 7/1/1992 | 6/30/2002 |
| Cleanup - Construction | Canceled | 7/1/1992 | 12/30/1998 |
| Cleanup Action - Engineering Design | Canceled | 7/1/1992 | 12/30/1998 |
| LUST - Report Received | Completed | | 1/12/1993 |
| LUST - Report Received | Completed | | 4/25/1994 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 6/1/1994 | 6/30/1994 |
| Hazardous Sites Listing/NPL | Completed | | 6/30/1994 |
| LUST - Report Received | Completed | | 7/7/1998 |
| LUST - Report Received | Completed | | 1/11/2000 |
| LUST - Report Received | Completed | | 4/27/2001 |
| LUST - Report Received | Completed | | 11/26/2003 |
| LUST - Report Received | Completed | | 6/17/2005 |
| O & M | Canceled | 10/2/2006 | 6/20/2007 |
| Remedial Investigation and/or Feasibility Study | Completed | | 9/17/2018 |
| Cleanup Action Plan | Completed | | 9/17/2018 |