

# Cleanup Site Details

Cleanup Site ID: 5094

Cleanup Site ID: 5094      Facility/Site ID: 2346      UST ID: 618892      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Ballard Auto Wrecking      [Glossary](#)

Alternate Names: Ballard Auto Wrecking, BALLARD AUTO WRECKING FORMER

## LOCATION

Address: 1515 NW LEARY WAY      City: SEATTLE      Zip Code: 98107      County: King  
Latitude: 47.66346      Longitude: -122.37666      WRIA: 8      Legislative District: 36      Congressional District: 7      TRS: 25N 3E 11

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 7/12/2011      Current VCP? No      Past VCP? Yes  
Site Rank: 2 - Moderate-High Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Myers, Dale R      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Ballard Auto Wrecking	Upland	No Further Action Required	NW	Myers, Dale R	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Halogenated Organics	B	B				
Metals Priority Pollutants	RB	B				
Non-Halogenated Solvents	RB	RB				
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Petroleum-Other	RB	RB				
Polychlorinated biPhenyls (PCB)	B	B				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	7/26/1996	12/20/1996
Hazardous Sites Listing/NPL	Completed		2/28/1997
LUST - Report Received	Completed		3/17/2003

# Cleanup Site Details

Cleanup Site ID: 5094

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Cleanup Action	Completed	3/17/2003	6/29/2004
LUST - Notification	Completed		5/21/2003
LUST - Report Received	Completed		7/9/2003
LUST - Report Received	Completed		3/3/2004
VCP Opinion on Cleanup Action	Completed	1/21/2009	4/21/2009
Periodic Review	Completed	10/30/2010	1/17/2011
VCP Receipt of Plan or Report	Completed		5/2/2011
LUST - Report Received	Completed		5/2/2011
VCP Opinion on Site Cleanup	Completed	5/2/2011	7/12/2011
Site Status Changed to NFA	Completed		7/12/2011
Remove site from Hazardous Sites List	Completed		11/21/2011
LUST - Report Received	Completed		10/30/2014