Cleanup Site Details

Cleanup Site ID: 5182

Cleanup Site ID: 5182 **Facility/Site ID:** 2728 **UST ID:** 200920 Site Page | Site Documents | View Map

Cleanup Site Name: ExxonMobil ADC Glossary

Alternate Names: AMERICAN DISTRIBUTING, Exxon Bulk Storage, ExxonMobil ADC, ExxonMobil ADC Site, EXXONMOBIL BULK PLANT, MILLER AMERICAN DISTR MOBIL, MOBIL EVERETT, MOBIL OIL BULK PLANT 46 108, MOBIL OIL EVERETT BULK PLANT, MOBIL OIL MARKETING TERM, MOBIL OIL MARKETING TERMINAL

LOCATION

Address: 2717 & 2731 FEDERAL AVE **City:** EVERETT **Zip Code:** 98201 **County:** Snohomish

Latitude: 47.98166 **Longitude:** -122.21668 **WRIA:** 7 **Legislative District:** 38 **Congressional District:** 2 **TRS:** 29N 5E 19

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No

Site Manager: Cook, Jason **Responsible Unit:** Headquarters **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bulk Petroleum Storage Operations	Upland	Cleanup Started	HQ	Cook, Jason	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Benzene		C				
Non-Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				
Polycyclic Aromatic Hydrocarbons	C					

Key:
B - Below Cleanup Level
C - Confirmed Above Cleanup Level
RA - Remediated-Above
S - Suspected
R - Remediated
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Initial Investigation / Federal Preliminary Assessment	Completed		5/31/1985
Interim Action	Completed	5/1/1988	5/31/1988
LUST - Report Received	Completed		5/2/1988

Cleanup Site Details

Cleanup Site ID: 5182

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		8/25/1988
Interim Action	Completed	3/1/1989	3/31/1989
LUST - Notification	Completed		4/3/1989
LUST - Report Received	Completed		6/12/1990
LUST - Report Received	Completed		11/16/1990
LUST - Report Received	Completed		4/2/1991
LUST - Report Received	Completed		6/5/1991
Interim Action	Completed	12/8/1993	12/31/1993
Early Notice Letter(s)	Completed		1/12/1995
Site Discovery/Release Report Received	Completed		7/18/1995
Initial Investigation / Federal Preliminary Assessment	Completed		7/20/1995
Emergency Action	Completed	11/10/1995	12/30/1997
Site Hazard Assessment/Federal Site Inspection	Completed	2/23/1996	6/28/1996
Hazardous Sites Listing/NPL	Completed		8/20/1996
Early Notice Letter(s)	Completed		12/6/1996
Order/Decree/Amendment	Completed		12/30/1997
Remedial Investigation and/or Feasibility Study	Completed	1/1/1998	7/23/1998
Interim Action	Completed	10/7/1998	2/28/2000
Interim Action - Performance Monitoring	In Process	3/1/2002	
LUST - Report Received	Completed		5/14/2004
Remedial Investigation and/or FS Work Plan	Completed	10/6/2008	3/1/2010
Interim Action - Plan	Completed	3/3/2010	5/17/2010
Order/Decree/Amendment	Completed		3/24/2010
Remedial Investigation and/or Feasibility Study	In Process	6/21/2010	
Interim Action - Construction	Completed	6/27/2010	8/26/2011