

Cleanup Site ID: 536

## Cleanup Site Details

Facility/Site ID: 199 UST ID: 2837 Site Page Site Documents View Map

Cleanup Site ID: 536

Cleanup Site Name: US DOE BPA Ross Complex

Glossary

Alternate Names: BPA ROSS COMPLEX, Ross Complex, US BPA ROSS COMPLEX, US DOE BPA Ross Complex

LOCATION

Address: 5411 NE HWY 99 City: VANCOUVER Zip Code: 98666 County: Clark

Latitude: 45.66188 Longitude: -122.66520 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS: 2N 1E 15

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: Federal - CERCLA NFA Date: 1/27/1996 Current VCP? No Past VCP? No

Site Rank: 0 - NPL Site (Fed HRS Score) NFA Reason: Federal Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Rogowski, Barry Responsible Unit: EPA Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ROSS COMPLEX	Upland	No Further Action Required	EPA	Rogowski, Barry	Federal-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	R					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/1/1993
Hazardous Sites Listing/NPL	Completed		8/31/1993
Remove site from Hazardous Sites List	Completed		1/27/1996
Site Status Changed to NFA	Completed		1/27/1996

Toxics Cleanup Program Report Generated: 4/25/2024 Page 1 of 1